

NAPAKIAK (WNA)(PANA) 0 W UTC-9(-8DT) N60°41.42' W161°58.71'

BETHEL
L-3C
IAP

17 B NOTAM FILE WNA

RWY 16-34: 3248X60 (GRVL) MIRL

RWY 16: REIL. PAPI(P4L)—GA 3.0° TCH 26'. Brush.

RWY 34: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Brush.

SERVICE: LGT ACTIVATE MIRL Rwy 16-34, REIL Rwy 16 and Rwy 34, PAPI Rwy 16 and Rwy 34 and rotating bcn—CTAF. Rwy 16-34 rwy lgts obscured by brush.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Numerous arpts invof WNA. Rwy 16-34 sfc ruts at end of rwys due to acft turning around. Rough spots in parking area. Rwy 16-34 south 1500' 6" dips. Deep ruts in the south side of ramp. Windsock unreliable. Rwy 16 and 34 NSTD mkg: rwy mkd with lights, cones, and thld panels.

AIRPORT MANAGER: (907) 543-2498

WEATHER DATA SOURCES: AWOS-3P 121.425 (907) 868-7321. (WX CAM)

COMMUNICATIONS: CTAF 122.9


ANCHORAGE CENTER APP/DEP CON 125.2

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) VORTACW 114.1 BET Chan 88 N60°47.09'

W161°49.46' 205° 7.3 NM to fld. 105/14E.

COMM/NAV/WEATHER REMARKS: For a toll-free call to Kenai FSS dial 1-866-864-1737.



NAPASKIAK (PKA)(PAPK) 1 SW UTC-9(-8DT) N60°42.17' W161°46.70'

BETHEL
L-3C
IAP

11 B NOTAM FILE ENA

RWY 02-20: 3000X60 (GRVL) MIRL

RWY 02: Brush.

RWY 20: Brush.

SERVICE: LGT ACTVT MIRL Rwy 02-20—CTAF.

AIRPORT REMARKS: Unattended. Rwy 02-20 condition not monitored, recommend visual inspection prior to use. Rwy 02-20 floods in spring. Barge landing site north end of rwy. Machinery and large supplies may be stored in area. Windsocks unreliable.

AIRPORT MANAGER: (907) 543-2498

COMMUNICATIONS: CTAF 122.9


ANCHORAGE CENTER APP/DEP CON 125.2

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) VORTACW 114.1 BET Chan 88 N60°47.09'

W161°49.46' 151° 5.1 NM to fld. 105/14E.

COMM/NAV/WEATHER REMARKS: For a toll-free call to Kenai FSS dial 1-866-864-1737.



WATERWAY 09W-27W: 15000X2000 (WATER)

SEAPLANE REMARKS: Unattended. Watch for nets and boats in river area in front of village unusable for float planes. Soft muddy beach.

NAUKATI BAY SPB (See TUXEKAN ISLAND on page 253)