

ATMAUTLUAK (4A2) 0 NE UTC-9(-8DT) N60°52.07' W162°16.46'
19 B NOTAM FILE ENA
RWY 15-33: 3000X75 (GRVL) MIRL

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Brush.

RWY 33: REIL. PAPI(P4L)—GA 3.0° TCH 24'. Brush.

SERVICE: LGT ACTIVATE MIRL Rwy 15-33 and PAPI and REIL Rwy 15 and Rwy 33—CTAF.

AIRPORT REMARKS: Unattended. Rwy width varies. Rwy condition not monitored, recommend visual inspection prior to using. First 650' of Rwy 33 rough with dips. Rwy, twy and ramp dips and ruts 4-6'. Rwy sinking and sloped towards East. Safety areas rough. Birds invof rwy.

AIRPORT MANAGER: (907) 543-2498


COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) VORTAC 114.1 BET Chan 88 N60°47.09'
W161°49.46' 277° 14.1 NM to fld. 105/14E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

BETHEL
L-3C



ATQASUK EDWARD BURNELL SR MEML (ATK)(PATQ) 1 S UTC-9(-8DT) N70°28.03'
W157°26.14'

101 B NOTAM FILE ATK

RWY 07-25: 4370X90 (GRVL) MIRL

RWY 07: REIL. PAPI(P2L)—GA 3.0° TCH 30'.

RWY 25: REIL. PAPI(P2L)—GA 3.0° TCH 30'.

SERVICE: LGT ACTVT REIL Rwy 07 and 25; PAPI Rwy 07 and 25; MIRL Rwy 07-25—CTAF.

AIRPORT REMARKS: Unattended. Abandoned rwy N side of community visible. Several 6 inch deep ruts 1800 ft from Rwy 25 thld. Rwy condition not monitored; recommend visual inspection prior to using. Rwy surface 90 ft-110 ft between edge lights. Cold temperature restricted airport. Altitude correction required at or below -43C.

AIRPORT MANAGER: (907) 852-0489

WEATHER DATA SOURCES: AWOS-3P 119.925 (907) 633-2012.

COMMUNICATIONS: CTAF 122.9


ANCHORAGE CENTER APP/DEP CON 135.3

RADIO AIDS TO NAVIGATION: NOTAM FILE ATK.

NDB (HW) 350 ATK N70°28.14' W157°25.65' at fld. 97/16E.

COMM/NAV/WEATHER REMARKS: Local call to Barrow FSS dial 852-2511. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

CAPE LISBURNE
H-1A, L-4I
IAP



BADAMI (See DEADHORSE on page 92)