TROY		
REI	ISSELAER CO (5B7) 6 SE UTC-5(-4DT) N42°41.50' W73°34.80' 140 NOTAM FILE BTV IWY 18-36: H2670X50 (ASPH) S-8 RWY 18: Trees. IRPORT REMARKS: Unattended. Tran acft call 518–596–5947 for fld conditions prior to arrival. De arpt. Surrounding terrain slopes down to rwy, due to higher surrounding terrain recommend us procedures, departing Rwy 36, use best angle of climb speed until well clear of residential area Rwy 18 maintain sufficient alt on final so as to avoid low alt and/or high power over residential apch to Rwy 18. Departures Rwy 18 and arrivals Rwy 36 use normal procedures. Rwy 18–34 and distortion. Svr spalling and faulting. Widespread vegetation. Rwy 18 first 40' overgrown with not visible. Rwy 36 marking numbers faded. URPORT MANAGER: (518) 596-5947 SOMMUNICATIONS: CTAF/UNICOM 122.7 LEARAKCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.	se of the following a north of Rwy 36, arrivals area which underlies final 5 widespread svr cracking
FR/	FRANKFORT   INKFORT-HIGHLAND (6B4) 4 SE UTC-5(-4DT) N43°00.97' W75°10.17'   I325 NOTAM FILE BUF UTC-5(-4DT) N43°00.97' W75°10.17'   IWY 13-31: H2750X60 (ASPH) S-12 LIRL 0.4% up NW   RWY 31: ThId dspicd 200'. Trees. RWY 31: Thid dspicd 205'. ERVICE: FUEL 100LL   IRPORT REMARKS: Unattended. Self-serve fuel. Geese on and invof arpt during spring and fall. Mod Rwy 31 has 120' dropoff 90' from thid on both sides. LIRL Rwy 13-31 not avbi to tran acft   IRPORT MANAGER: 315-796-6257 EXAMPLE TO TABLE	
	CA N43°01.59´W75°09.87´ NOTAM FILE BUF. L) TACAN 111.2 UCA Chan 49 319° 16.4 NM to Griffiss Intl. 1420/OW. ICO 122.2 (BUFFALO RADIO)	NEW YOUF L-320
	LL SELT (N45) 2 NE UTC-5(-4DT) N41°37.45' W74°08.50' 120 B NOTAM FILE ISP WWY 03-21: H2864X50 (ASPH) S-13 RWY 03: Trees. RWY 21: Trees. IRPORT REMARKS: Unattended. Arpt clsd to acft 13,500 lbs and over. Deer on and invof arpt. PJE SFC-14,500'. Rwy 03 has access road 16' from thId both sides. Rwy center width of 30' in ; on both sides of centerline in poor condition with extensive cracks and vegetation. Rwy 03-21 areas opposite south end of rwy. Rwy center 30' in fair condition, outside edges beyond this in parallel twy, stub connectors to rwy between ends in poor condition.	good condition, 10' width slight depression in grass

AIRPORT MANAGER: 914-548-3028 Communications: CTAF/Unicom 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.