

MOLOKAI (MKK)(PHMK) 6 NW UTC-10 N21°09.17' W157°05.78'
454 B TPA—See Remarks Class I, ARFF Index A NOTAM FILE MKK
RWY 05-23: H4494X100 (ASPH-GRVD) S-30, D-48 PCN 12 F/B/Y/T MIRL

HAWAIIAN ISLANDS

P-2G

IAP, AD

0.4% up NE

RWY 05: REIL. PAPI(P4L)—GA 4.0° TCH 49'

RWY 23: H3118X100 (ASPH) S-13 PCN 11 F/B/Y/T MIRL

0.6% up N

RWY 17: Thld dsplcd 426'. Fence.

RWY 35: Fence.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-4494 TODA-4494 ASDA-4494 LDA-4494

RWY 17: TORA-3118 TODA-3118 ASDA-3118 LDA-2692

RWY 23: TORA-4494 TODA-4494 ASDA-4494 LDA-3901

RWY 35: TORA-3118 TODA-3118 ASDA-3118 LDA-3118

SERVICE: LGT When twr closed ACTIVATE MIRL Rwy 05-23 and Rwy 17-35, REIL Rwy 05—CTAF. Rwy 05 PAPI not authorized 1.8 NM byd landing thld due to rapidly rising terrain.

AIRPORT REMARKS: Attended 1500-0615Z. Be alert to egrets and pigeons on and in vicinity of arpt. TPA—small acft 1250(796) large acft 1950(1496). Arpt CLOSED to air carrier operations with more than 10 passenger seats 0530-1600Z except PPR call (808) 567-9660/9663. 24 hrs PPR for Division 1.1, 1.2, 1.3 explosives and 4 hrs PPR for other hazardous material in/out of arpt ctc (808) 567-6140/6008. Large acft with wingspan greater than 78' may not use Twy A or Rwy 05-23 for simultaneous ops. Mountain approximately 1280' MSL located 2.8 NM from threshold Rwy 05 on extended centerline. Standing water/ponding on Rwy 17-35 near Twy Echo during inclement weather.

AIRPORT MANAGER: (808) 872-3808

WEATHER DATA SOURCES: ASOS (808) 567-6106

COMMUNICATIONS: CTAF 125.7 ATIS 128.2

MOLOKAI RCO 122.1R 116.1T (HONOLULU RADIO)

® **HCF CENTER APP/DEP CON** 124.1

TOWER 125.7 (1600-0430Z) **GND CON** 121.9

AIRSPACE: CLASS D svc 1600-0430Z other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE MKK.

(H) **VORTAC** 116.1 MKK Chan 108 N21°08.29' W157°10.05' 067° 4.1 NM to fld. 1421/11E.

VORTAC unusable:

275°-285° byd 25 NM blo 3,500'

