

DOUBLE SPRINGS/WINSTON CO (3M2) 4 E UTC-6(-5DT) N34°08.65' W87°19.67'

ATLANTA
L-18H

754 NOTAM FILE ANB

RWY 03-21: H3331X78 (ASPH) S-15 MIRL

RWY 03: Thld dsplcd 216'. Trees.

SERVICE: LGT Lgt sys inop. Bcn SS-SR.

AIRPORT REMARKS: Unattended. Rwy 03-21 wdspr cracking with vegetation. Lrg area of ramp is unsafe for acft due to pavement failure.


AIRPORT MANAGER: 205-489-5318

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Memphis ARTCC at 901-368-8453.

RADIO AIDS TO NAVIGATION: NOTAM FILE ANB.

HAMILTON (L) DME 110.4 HAB Chan 41 N34°11.93'
W88°00.70' 095° 34.2 NM to fld. 802/OE.



ELBA

CARL FOLSOM (14J) 2 W UTC-6(-5DT) N31°24.60' W86°05.42'

NEW ORLEANS
L-22H

258 B NOTAM FILE ANB

RWY 01-19: H3050X75 (ASPH) S-4 MIRL

RWY 01: Tree.

RWY 19: Pole.

SERVICE: FUEL 100LL LGT After dusk ACTVT MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Unattended. Fuel 24 hr credit card svc avbl. Rwy 01-19 has 344' by 100' asph overrun on the north end. Rwy 01-19 clsd to hel mov skid ldg. Rwy 19 markings faded or obsc.

AIRPORT MANAGER: 334-897-2349

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Cairns Apch at 334-255-8402 or 334-255-8460, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE ANB.

WIREGRASS (L) VORTACW 111.6 RRS Chan 53 N31°17.08'
W85°25.87' 281° 34.7 NM to fld. 345/2E.

VOR unusable:

326°-336° byd 15 NM blo 1,900'

326°-336° byd 20 NM blo 2,300'

326°-336° byd 30 NM blo 4,000'

337°-350° byd 13 NM blo 4,000'

337°-350° byd 20 NM blo 6,000'

337°-350° byd 30

