EAST HADDAM

GOODSPEED (42B) 1 SE UTC–5(–4DT) N41°26.74′ W72°27.34′ **NEW YORK**
9 NOTAM FILE BDR
RWY 14–32: H2120X50 (ASPH) S–8 LIRL
RWY 32: Trees.
SERVICE: S4 **LGT** Arpt lgts opr 24 hrs.
AIRPORT REMARKS: Unattended. Caution deer, birds and waterfowl on and invof arpt. Parl turf twy mkd with yellow cones. May be soft when wet or aft rain. Seaplane dock and ramp. Overnight parking fee. Ldg fee.
AIRPORT MANAGER: (860) 615-9068
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449.

• • • • • • • • • • • • • • • • • •

WATERWAY 16W–34W: 4500X1000 (WATER)
WATERWAY 16W: Bridge.
WATERWAY 34W: Hill.

ELLINGTON (7B9) 2 N UTC–5(–4DT) N41°55.53′ W72°27.43′ **NEW YORK**
253 NOTAM FILE BDR
RWY 01–19: H1800X50 (ASPH) S–9 RWY LGTS(NSTD)
RWY 01: Trees.
RWY 19: Trees.
SERVICE: S4 **FUEL** 100LL **LGT** Non–std LIRL opr dusk–0500Z‡, for lgts aft 0500Z‡ call 860–871–2054 durg bus hrs. Rwy 01–19 non–std LIRL due to spacing, thr lgts outboard of rwy.
AIRPORT REMARKS: Attended 1300–2300Z‡. Parachute Jumping. Extensive helicopter training ops. Acft tfc pat on E side of arpt only. Hel tfc pat on W side of arpt only. Twy pavement failed, extsv cracking, patches, loose aggregate and sml stones. Rwy 01 mkgs faded. Rwy 19 mkgs faded.
AIRPORT MANAGER: 860-614-1854
COMMUNICATIONS: CTAF/UNICOM 123.0
CLEARANCE DELIVERY PHONE: For CD ctc Bradley Apch at 860-386-3597.

FARMINGTON CT71 N41°42.54′ W72°48.13′/363 **NEW YORK**
AWOS–AV 129.825 AWOS–AV wx bcst on 129.825 (3 mic clicks). **L–33C, 34I**

GOODSPEED (See EAST HADDAM on page 35)