COLUMBIA/MARION CO (ØRØ) 3 N UTC–6(–5DT) N31°17.87′ W89°48.69′
270 B NOTAM FILE GWO

RWY 05–23: H5500X100 (ASPH–GRVD) S–63, D–90, 2D–174 PCN 23 F/B/X/T MIRL 0.5% up NE
RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 42′. Trees.
RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 43′. Tree.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** ACTVT REIL Rwy 05 and 23; MIRL Rwy 05–23—CTAF. PAPI Rwy 05 and 23 opr consly.

AIRPORT REMARKS: Attended on call. For svc call 601–441–0299 or 601–441–1867. Fuel svc avbl 24 hrs with credit card. Pub fone avbl 601–736–9295.

AIRPORT MANAGER: 601-736-9295

WEATHER DATA SOURCES: AWOS–3PT 120.675 (601) 736–4983.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **HOUSTON CENTER APP/DEP CON** 126.8

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE GWO.

EATON (L) (L) VORTACW 110.6 LBY Chan 43 N31°25.12′ W89°20.26′ 249° 25.4 NM to fld. 290/5E.

VOR unusable:
010°–036° byd 30 NM
010°–036° byd 6 NM blo 15,000′
111°–164° byd 10 NM blo 2,000′
241°–251°
300°–000° byd 30 NM

TACAN AZIMUTH unusable:
010°–036° byd 30 NM
010°–036° byd 6 NM blo 15,000′
300°–000° byd 30 NM

DME unusable:
268°–274° byd 30 NM blo 5,000′
300°–000° byd 30 NM

