EVANSVILLE

EVANSVILLE RGNL (EVV)(KEVV) 3 N UTC–6(–5DT) N38º02.45´ W87º31.71´ **ST LOUIS**
422 B ARFF Index—See Remarks NOTAM FILE EVV MON Airport **H–5E, L–16I**
RWY 04–22: H8021X150 (ASPH–GRVD) S–100, D–175, 2S–175, 2D–300 PCR 660 F/B/X/T HIRL **IAP, AD**
RWY 04: REIL. PAPI(P4R)—GA 3.0º TCH 49´. RVR–R Tree. 0.3% up.
RWY 22: MALSR. RVR–T Pole. 0.6% down.
RWY 18–36: H6286X150 (ASPH–GRVD) S–100, D–175, 2S–175, 2D–300 PCR 1049/F/B/X/T HIRL
RWY 18: REIL. PAPI(P4R)—GA 3.0º TCH 49´. Pole.
RWY 36: REIL. PAPI(P4L)—GA 3.0º TCH 30´. Thld dsplcd 789´. Road.
RWY 09–27: H3497X75 (ASPH) S–30, D–40, 2D–60 PCN 3 F/B/Z/U MIRL
RWY 09: Thld dsplcd 529´. Road.
RWY 27: Thld dsplcd 218´. Road.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 04: TORA–8021 TODA–8021 ASDA–8021 LDA–8021
RWY 09: TORA–3497 TODA–3497 ASDA–3497 LDA–2968
RWY 18: TORA–5498 TODA–5498 ASDA–5498 LDA–5498
RWY 22: TORA–8021 TODA–8021 ASDA–8021 LDA–8021
RWY 27: TORA–3497 TODA–3497 ASDA–3497 LDA–3279
RWY 36: TORA–6287 TODA–6287 ASDA–6287 LDA–5498
SERVICE: S4 **FUEL** 100LL, JET A **OX** 3 **LGT** ACTVT MALSR Rwy 22; REIL Rwy 04, 18 and 36; PAPI Rwy 04; MIRL Rwy 09–27; HIRL Rwy 18–36—CTAF. When ATCT clsd HIRL Rwy 04–22 preset low ints; to incr ints—CTAF. Twy E lgts OTS.
AIRPORT REMARKS: Attended continuously. Birds on and invof arpt. Rwys 09–27 and Twy E rstrd to acft less than 50,000 lbs. Class I, ARFF Index B. Index C ARFF avbl O/R 812–421–4408.
AIRPORT MANAGER: 812-421-4401
WEATHER DATA SOURCES: ASOS 120.2 (812) 200–0105. LAWRS.
COMMUNICATIONS: CTAF 118.7 **ATIS** 120.2 **UNICOM** 122.95
Ⓡ **APP/DEP CON** 124.025 (041º–219º) 127.35 (220º–040º) (1200–0500Z‡)
Ⓡ **INDIANAPOLIS CENTER APP/DEP CON** 128.3 (220º–040º) (0500–1200Z‡)
TOWER 118.7 (1200–0500Z‡) **GND CON** 121.9 **CLNC DEL** 126.6
CLEARANCE DELIVERY PHONE: For CD when ATCT clsd ctc Indianapolis ARTCC at 317-247-2411.
AIRSPACE: CLASS C svc ctc **APP CON** svc 1200–0500Z‡; other times CLASS G.
RADIO AIDS TO NAVIGATION: NOTAM FILE HUF.
POCKET CITY (VH) (H) VORTACW 113.3 PXV Chan 80 N37º55.70´ W87º45.74´ 056º 13.0 NM to fld. 385/3E.
TACAN AZIMUTH unusable:
Byd 30 NM blo 2,600´
DME unusable:
Byd 30 NM blo 2,600´
VOR unusable:
030º–034º byd 40 NM
046º–055º byd 40 NM
098º–102º byd 40 NM
106º–109º byd 40 NM
ILS/DME 109.9 I–DSO Chan 36 Rwy 04. Class IA. Unmonitored when ATCT clsd.
ILS/DME 109.9 I–EVV Chan 36 Rwy 22. Class IB. Unmonitored when ATCT clsd. DME unusable 25º left of course.
ASR (1200–0500Z‡)

SKYLANE (3EV) 1 NW UTC–6(–5DT) N38º00.72´ W87º35.69´ **ST LOUIS**
380 NOTAM FILE HUF
RWY 18–36: 2227X142 (TURF)
RWY 18: Tree.
RWY 36: Tree.
SERVICE: S2 **FUEL** 100LL
AIRPORT REMARKS: Attended irregularly. Coordinate ingress/egress with Evansville App/Dep Ctl. Rwy 18–36 mkd with L shaped mats painted white. 400 ft stopway north end, 500 ft stopway south end. Rwy 18–36 use at night NA.
AIRPORT MANAGER: (812) 480-2152
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Evansville Apch at 812-436-4690, when Apch clsd ctc Indianapolis ARTCC at 317-247-2411.