UNIVERSITY AIRPARK (See BATH on page 155)

VAN CAMP'S HELIPORT (See TECUMSEH on page 245)

VAN EFFEN FLD (See ROCK on page 231)

VAN WAGNEN (See NAPOLEON on page 221)

VICTORY N42°47.20′ W85°29.82′ NOTAM FILE GRR. CHICAGO
(VH) (H) VORW/DME 115.95 VIO Chan 106(Y) 353° 5.8 NM to Gerald R Ford Intl. 802/4W. DME unmonitored. H–5E, 10F, L–28
DME unusable:
011°–314° byd 30 NM blo 3,000′
VOR unusable:
140°–150° byd 40 NM
255°–260° byd 40 NM blo 6,000′
255°–260° byd 56 NM

VIRGIL L WILLIAMS PLAINWELL MUNI (See PLAINWELL on page 228)

WATERVLIET MUNI (4ØC) 1 NNE UTC–5(–4DT) N42°12.04′ W86°14.96′ CHICAGO
656 NOTAM FILE LAN
RWY 02–20: 2600X200 (TURF) MIRL
RWY 02: Thld dsplcd 600′. Trees.
RWY 20: Thld dsplcd 800′. Trees.
RWY 07–25: 1540X200 (TURF)
RWY 07: Trees.
RWY 25: Trees.
SERVICE: **LGT** ACTVT MIRL Rwy 02–20—CTAF.
AIRPORT REMARKS: Unattended. No sn removal. For ficons ctc amgr. Deer, birds, and wildlife on and invof arpt. UAS, ultralight, and power prcht act. Rwy 07–25 unverified ldg area – ctc amgr for dtls. Rwy 02–20 soft when wet and durg spring due to poor drainage. Rwy 02–20 and dthr mkd with 3′ yellow cones. Rwy 07–25 soft when wet and durg spring due to poor drainage. Rwy 07–25 defined by mowing. Hospital hlp 1 nm S. Admin bldg aces H24.
AIRPORT MANAGER: 269-757-1180
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

WAYLAND

CALKINS FLD (41C) 1 N UTC–5(–4DT) N42°41.49′ W85°38.84′ CHICAGO
754 NOTAM FILE LAN
RWY 09–27: 1800X100 (TURF)
RWY 09: Thld dsplcd 260′. Crops.
RWY 27: Crops.
AIRPORT REMARKS: Unattended. Deer, birds, and wildlife on and invof arpt. No sn removal — ctc amgr to vfy conds. Rwy 09–27 soft when wet. Rwy 09 rwy and dthr mkd with 3′ yellow cones. Rwy 27 mkd by 3′ yellow cones.
AIRPORT MANAGER: 616-889-5971
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3344, when Apch clsd ctc Chicago ARTCC at 630-906-8921.

WEIDMAN

OJIBWA AIRPARK (D11) 3 NW UTC–5(–4DT) N43°43.24′ W85°00.13′ CHICAGO
959 NOTAM FILE LAN
RWY 05–23: 3600X125 (TURF) LIRL 0.6% up SW
RWY 05: Thld dsplcd 1000′. Fence.
RWY 23: Thld dsplcd 400′. Trees.
SERVICE: **LGT** Rwy lgts SS–SR Apr–Nov; PCL on CTAF Dec–Mar.
AIRPORT REMARKS: Attended Apr–Nov irregularly. For ficons call asst amgr 989–330–3575. Arpt CLOSED aprxly Nov—Apr when snow covd except for ski equipped acft. UAS oper at midfield, near trml bldg. Trees and bldgs both sides of rwy. Deer, birds, and wildlife on and invof arpt. Rwy 05–23 and dthr mkd with 3′ yellow cones. Rwy 05–23 rwy surface east 400 ft soft when wet. Trml bldg access: 5–3–2–1.
AIRPORT MANAGER: 586-805-0853
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.