

COLUMBIA (4G8) 1 WNW UTC-5(-4DT) N41°19.12' W81°57.63'	DETROIT
811 NOTAM FILE CLE	L-30G
RWY 18-36: H3152X40 (ASPH) LIRL(NSTD)	
RWY 18: Thld dsplcd 300'. Trees.	
RWY 36: Thld dsplcd 209'. Tree.	
SERVICE: LGT NSTD LIRL Rwy 18-36 OTS indefly. Rwy 18-36 NSTD LIRL due to misg thr lgts.	
AIRPORT REMARKS: Attended Mon-Fri 1400-2200Z; Sat-Sun irreg. Unatndd major hols. Rwy 18-36 clsd dly SS-SR. Ocnl deer, birds, & otr wildlife on & invof arpt. Rwy end 18: nstd nrs only due to no dthr mkgs, no arrowheads; north 300 ft unmkd. Rwy end 36: nstd nrs only due to no dthr mkgs, no arrowheads; north 300 ft unmkd.	
AIRPORT MANAGER: 757-510-6788	
COMMUNICATIONS: CTAF/UNICOM 122.8	
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.	
RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.	
DRYER (VH) (DH) VORW/DME 113.6 DJB Chan 83 N41°21.48' W82°09.72' 109° 9.4 NM to fld. 780/5W.	
VOR unusable:	
001°-010° byd 40 NM	
020°-024° byd 40 NM	
080°-095° byd 40 NM	
110°-120° byd 40 NM	
135°-150°	
155°-165°	
185°-197°	
210°-218°	
219°-224° byd 40 NM	
225°-235° byd 40 NM blo 11,000'	
225°-235° byd 95 NM	
225°-245° byd 20 NM blo 3,500'	
246°-257° byd 40 NM	
286°-355° byd 40 NM	
DME unusable:	
187°-197°	
289°-310°	
322°-332°	
350°-060°	

COLUMBIANA CO (See EAST LIVERPOOL on page 279)
