COLUMBUS

BOLTON FLD (TZR)(KTZR) 7 WSW UTC–5(–4DT) N39°54.07′ W83°08.22′ **CINCINNATI**
904 B TPA—1704(800) NOTAM FILE TZR **H–10G, L–29A**
RWY 04–22: H5500X100 (ASPH) S–93, D–156, 2S–95, 2D–258 PCR 364 F/B/X/T MIRL **IAP, AD**
RWY 04: MALSR. PAPI(P4L)—GA 3.0° TCH 25′.
RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 25′.
SERVICE: S4 **FUEL** 100LL, JET A1+ **OX** 3 **LGT** When ATCT clsd ACTVT MALSR Rwy 04; REIL Rwy 22; MIRL Rwy 04–22—CTAF.
AIRPORT REMARKS: Attended 1230–0030Z‡. Birds & otr wildlife on & invof arpt. Bln & banner act on & invof arpt. 100LL avbl H24 self svc via credit card. High tension plines/towers NE–SE. Calm wind Rwy 04.
AIRPORT MANAGER: 614-851-9900
WEATHER DATA SOURCES: AWOS–3PT 135.925 (614) 878–1722. Freq unavbl 1230–0030Z‡ ctc gnd ctl 121.8 for wx.
COMMUNICATIONS: CTAF 128.1
Ⓡ **COLUMBUS APP/DEP CON** 134.0
TOWER 128.1 (1230–0030Z‡) **GND CON** 121.8
CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Columbus Apch at 614-338-8537.
AIRSPACE: CLASS D svc 1230–0030Z‡; other times CLASS G.
RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.
APPLETON (VH) (H) VORTACW 116.7 APE Chan 114 N40°09.06′ W82°35.30′ 246° 29.4 NM to fld. 1354/6W.
VOR unusable:
025°–030°
TACAN AZIMUTH unusable:
075°–095°
110°–115°
DME unusable:
075°–080°
BOUTN NDB (MHW/LOM) 230 BU N39°49.16′ W83°12.28′ 037° 5.8 NM to fld. 922/5W. NDB unmonitored 0200–1400Z‡.
NDB unusable:
355°–010° byd 15 NM
ILS 111.7 I–BUZ Rwy 04. LOM BOUTN NDB. Unmonitored when ATCT clsd. Glideslope unmonitored when ATCT clsd. BOUTN NDB unusable 357°–027° byd 10 NM. Autopilot coupled approach NA below 1,144 feet. Glideslope reversal at 0.61 NM from threshold.
COMM/NAV/WEATHER REMARKS: Emerg frequency not monitored all times. For fuel and acft svcs ctc FBO on 123.3.

