

OHIO STATE UNIVERSITY (OSU)(KOSU) P (NG) 10 NW UTC-5(-4DT) N40°04.77' W83°04.39' **DETROIT**
 906 B Class IV, ARFF Index A NOTAM FILE OSU **H-10G, L-29A**
RWY 09R-27L: H5004X100 (ASPH-GRVD) S-120, D-250, 2D-550, 2D/2D2-1061 PCR 860 F/C/X/T **IAP, AD**
 HIRL No Part 121/Part 380 Ops
RWY 09R: MALSR. PAPI(P4L)—GA 3.0° TCH 51'.
RWY 27L: REIL. PAPI(P4L)—GA 3.0° TCH 28'. Tree.
RWY 05-23: H3562X100 (ASPH) S-76, D-122, 2D-206 PCR 290 F/B/X/T 0.3% up SW No Part 121/Part 380 Ops
RWY 05: Trees.
RWY 23: Trees.
RWY 09L-27R: H2994X100 (ASPH) S-63, D-91, 2D-154 PCR 240 F/C/X/T MIRL 0.4% up W No Part 121/Part 380 Ops
RWY 09L: VASI(V2L)—GA 3.0° TCH 27'.
RWY 27R: VASI(V2L)—GA 3.0° TCH 31'. Trees.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 05: TORA-3562 TODA-3562 ASDA-3562 LDA-3562
RWY 09L: TORA-2994 TODA-2994 ASDA-2994 LDA-2994
RWY 09R: TORA-5004 TODA-5004 ASDA-5004 LDA-5004
RWY 23: TORA-3562 TODA-3562 ASDA-3562 LDA-3562
RWY 27L: TORA-5004 TODA-5004 ASDA-5004 LDA-5004
RWY 27R: TORA-2994 TODA-2994 ASDA-2994 LDA-2994
SERVICE: S4 **FUEL** 100LL, JET A1+ **OX** 1, 2 **LGT** When ATCT clsd ACTVT MALSR Rwy 09R—CTAF. REIL Rwy 27L;
 PAPI Rwy 09R & 27L; VASI Rwy 09L & 27R; HIRL Rwy 09R-27L – opr consly med instst. MIRL Rwy 09L-27R – opr
 consly low instst. **MILITARY—FUEL** (NC-100LL, A1+)
NOISE: Noise sensitive area within 4 miles to the north and northeast. Noise abatement rstrns: No TGL or rptd tkof/Indg
 0400-1200Z± dly.
AIRPORT REMARKS: Attended 1100-0400Z±. Birds & deer on & invof arpt. Sfc conds unmon 0400-1200Z±. Rwy 05-23
 CLOSED dly SS-SR. All twys north of Rwy 09R-27L clsd to unsked ACR ops gtr than 30 pax seats. Clsd to Part 121 skedd
 ACR ops gtr than 9 pax seats; 90 day PPR for unsked ACR ops gtr than 30 pax seats—call amgr. Rwy 05-23, Rwy
 09L-27R and Rwy 09R-27L, 90 day PPR for unsked ACR ops gtr than 30 pax seats—call amgr. Closed ramp north of
 Twy G 24 hour PPR for use 614-292-5617. Snow removal operating procedures: when twr clsd, announce arrs/deps on
 freq 118.8.
AIRPORT MANAGER: 614-292-4229
WEATHER DATA SOURCES: ASOS 121.35 (614) 451-2465. LAWRS.
COMMUNICATIONS: CTAF 118.8 ATIS 121.35 UNICOM 122.95
 ® **COLUMBUS APP/DEP CON** 125.95
STATE TOWER 118.8 (1200-0400Z±) **GND CON** 121.7 **CLNC DEL** 121.7
AIRSPACE: CLASS D svc 1200-0400Z±; other times CLASS G.
RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.
APPLETON (VH) (H) VORTACW 116.7 APE Chan 114 N40°09.06' W82°35.30' 265° 22.7 NM to fld. 1354/6W.
 VOR unusable:
 025°-030°
 TACAN AZIMUTH unusable:
 075°-095°
 110°-115°
 DME unusable:
 075°-080°
FULER NDB (MHW/LOM) 515 OS N40°04.42' W83°11.88' 091° 5.8 NM to fld. 941/5W. NOTAM FILE OSU.
 ILS 108.5 I-OSU Rwy 09R. Class IT. LOM FULER NDB. Unmonitored.
COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr.
 • • • • •
HELIPAD H1: H40X40 (ASPH)
HELIPORT REMARKS: Heliport (unlit) located north side of airfield, adjacent Air Guard ramp, Twy G. Helicopter Indgs/tkfs
 prohibited on Twy A and all ramp area south of Twy A. Helicopters ground taxi if capable on Twy A abeam ramp. When
 able, helicopters use 1900 MSL as traffic pattern altitude.