FOSTORIA

DONALD P MILLER (FZI)(KFZI) 2 NE UTC–5(–4DT) N41°11.45′ W83°23.59′ **DETROIT**
752 B NOTAM FILE CLE **H–11A, L–28J, 29A**
RWY 09–27: H5005X100 (ASPH) S–30, D–35, 2D–52 MIRL **IAP**
RWY 09: REIL. PAPI(P4L)—GA 3.0° TCH 25′. Trees.
RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 40′.
SERVICE: **FUEL** 100LL, JET A **LGT** ACTIVATE REIL Rwys 09 and 27; PAPI Rwy 09 and Rwy 27; MIRL Rwy 09–27—CTAF.
AIRPORT REMARKS: Attended 1300–2200Z‡
AIRPORT MANAGER: 419-435-0157
WEATHER DATA SOURCES: AWOS–3 124.625 (419) 436–0053.
COMMUNICATIONS: CTAF/UNICOM 122.7
Ⓡ**TOLEDO APP/DEP CON** 126.1
CLEARANCE DELIVERY PHONE: For CD ctc Toledo Apch at 419-865-1495.
RADIO AIDS TO NAVIGATION: NOTAM FILE FDY.
FLAG CITY (L) (L) VORTACW 108.2 FBC Chan 19 N40°57.32′ W83°45.36′ 051° 21.7 NM to fld. 823/2W.
DME unusable:
100°–125° byd 25 NM blo 4,000′

FREMONT

FREMONT (14G) 2 SW UTC–5(–4DT) N41°19.99′ W83°09.67′ **DETROIT**
663 NOTAM FILE CLE **L–28J**
RWY 09–27: H4137X60 (ASPH) S–13 LIRL **IAP**
RWY 09: Thld dsplcd 126′. Road.
RWY 27: Trees.
RWY 18–36: 2238X130 (TURF)
RWY 18: Trees.
RWY 36: Tree.
SERVICE: S4 **FUEL** 100LL **LGT** ACTVT LIRL Rwy 09–27 — 5 slow clicks CTAF.
AIRPORT REMARKS: Attended Mon–Sat 1400–2100Z‡, Sun 1700–2100Z‡. Deer & birds on & invof arpt. Aft hrs fuel 419–307–3111. Rwy 27 only 3390 ft lgtd. 3900 ft pavement avbl dalgt hrs. Publd rwy dimensions do not match pavement mrkgs. Rwy 09–27: outer 15 ft each side wdspr cracking, loose stones, and vegetation growth; cntr 30 ft fair cond. Rwy 27: white line marks rwy end, 330 ft of pavement east of line failed and unsuitable for acft due to wdspr svr cracking, dstns ovr 3 in, and wdspr vegetation growth. Rwy 27 nr faded. Rwy 09 nstd due white ln marks rwy end and dthr not mkd. Rwy 27 nstd due to white ln marks rwy end. Rwy 18–36 mowed 58 ft wide. East edge of rwy obstd by 60 ft trees, 50 ft fm cntrln, entr len of rwy. Windcone faded.
AIRPORT MANAGER: 419-307-3111
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ**TOLEDO APP/DEP CON** 126.1
CLEARANCE DELIVERY PHONE: For CD ctc Toledo Apch at 419-865-1495.
RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.
TIFFIN NDB (MHW) 269 TII N41°05.68′ W83°12.90′ 015° 14.5 NM to fld. 5W. NDB unmonitored.

SANDUSKY CO RGNL (S24) 5 SE UTC–5(–4DT) N41°17.75′ W83°02.23′ **DETROIT**
665 B NOTAM FILE S24 **H–10G, L–28J**
RWY 06–24: H5500X100 (ASPH–GRVD) S–30 MIRL **IAP**
RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 44′. Tree.
RWY 24: REIL. PAPI(P4L)—GA 3.0° TCH 42′.
SERVICE: **FUEL** 100LL, JET A+ **LGT** ACTVT REIL Rwy 06 & 24; PAPI Rwy 06 & 24; MIRL Rwy 06–24—CTAF.
AIRPORT REMARKS: Attended Mon–Sat 1300–2200Z‡. Unatndd major hols, after hrs call 419–547–0131. Birds and deer on and invof arpt. 100LL and Jet A+ avbl H24 self svc via credit card.
AIRPORT MANAGER: 419-547-0131
WEATHER DATA SOURCES: AWOS–3P 119.575 (419) 547–6932.
COMMUNICATIONS: CTAF/UNICOM 123.05
Ⓡ**TOLEDO APP/DEP CON** 126.1
CLEARANCE DELIVERY PHONE: For CD ctc Toledo Apch at 419-865-1495.
RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.
TIFFIN NDB (MHW) 269 TII N41°05.68′ W83°12.90′ 039° 14.5 NM to fld. 5W. NDB unmonitored.

FULER N40°04.42′ W83°11.88′ NOTAM FILE OSU. **DETROIT**
NDB (MHW/LOM) 515 OS 091° 5.8 NM to Ohio State University. 941/5W. **L–29A**

FULTON CO (See WAUSEON on page 316)