MIDDLETOWN RGNL/HOOK FLD (MWO)(KMWO) 2 N UTC–5(–4DT) N39°31.91′ W84°23.79′ **CINCINNATI**
651 B TPA—See Remarks NOTAM FILE MWO **H–10G, L–27E**
RWY 05–23: H6100X100 (ASPH) S–66, D–78, 2S–99, 2D–140 MIRL **IAP**
RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 22′. Trees.
RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 26′. Thld dsplcd 299′. Tree. Rgt tfc.
RWY 08–26: 3026X160 (TURF)
RWY 08: Thld dsplcd 951′. Trees.
RWY 26: Rgt tfc.
SERVICE: S4 **FUEL** 100LL, JET A+ **OX** 4 **LGT** ACTIVATE REIL Rwy 05 and Rwy 23; MIRL Rwy 05–23—CTAF. PAPI Rwy 05 and Rwy 23 opr consly.
AIRPORT REMARKS: Attended 1200–2400Z‡. For Jet A+ fuel aft hrs call 513–425–7845. Deer, birds, & otr wildlife on & invof arpt. Extensive Parachute Jumping. Ultralights enter/exit Rwy 08 tfc pat fm/to the North at lwr than rglr TPA. Ultralights do not fly south of Rwy 26. Rwy 08–26 end mkg white cones.
AIRPORT MANAGER: 513-705-1777
WEATHER DATA SOURCES: AWOS–3PT 120.025 (513) 422–3505.
COMMUNICATIONS: CTAF/UNICOM 123.0
Ⓡ **COLUMBUS APP/DEP CON** 118.85
CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.
RADIO AIDS TO NAVIGATION: NOTAM FILE HUF.
RICHMOND (L) DME 113.65 RID Chan 83(Y) N39°45.30′ W84°50.33′ 123° 24.5 NM to fld. 1135.
DME unusable:
025°–030° byd 35 NM
ONIDA NDB (LOMW) 223 MW N39°34.69′ W84°19.41′ 235° 4.4 NM to fld. 684/4W. NOTAM FILE DAY. NDB unmonitored.
NDB unusable:
060°–090° byd 10 NM
LOC 111.1 I–MWO Rwy 23. LOM ONIDA NDB. LOM unmonitored.

MIDWEST N39°25.78′ W83°48.07′ NOTAM FILE ILN. **CINCINNATI**
(T) (T) VORW/DME 112.9 MXQ Chan 76 at Wilmington Air Park. 1052/4W. **H–10G, L–27E**
VOR unusable:
051°–200°
201°–244° byd 10 NM blo 10,000′
245°–255° byd 20 NM blo 10,000′
256°–297° byd 18 NM blo 10,000′
298°–359°
300°–050° wi 3 NM
360°–022° blo 6,000′
360°–022° byd 18 NM blo 10,000′
DME unusable:
003°–024°
282°–302° byd 18 NM blo 4,000′
303°–309°
310°–320° byd 18 NM blo 6,000′
335°–340° byd 18 NM blo 6,000′

MILLER (See ALLIANCE on page 255)

MILLER FARM LANDING STRIP (See BALTIMORE on page 257)