
MYERS FLD (See CANBY on page 157)

NEW ULM MUNI (ULM)(KULM) 2 W UTC–6(–5DT) N44°19.10′ W94°30.10′ **OMAHA**
1011 B NOTAM FILE ULM **L–12I**
RWY 15–33: H5401X100 (ASPH–GRVD) MIRL **IAP**
RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 25′.
RWY 33: MALSF. PAPI(P4R)—GA 3.0° TCH 50′.
RWY 04–22: 2478X160 (TURF)
SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTVT MALSF Rwy 33; REIL Rwy 15; PAPI Rwy 15 and 33; MIRL Rwy 15–33—CTAF.
AIRPORT REMARKS: Attended Mon–Fri 1400–2300Z‡. 100LL fuel avbl H24 via credit card. Rwy 04–22 clsd winter months. Rwy 04 mkd with yellow cones. Rwy 22 mkd with yellow cones.
AIRPORT MANAGER: 507-233-2118
WEATHER DATA SOURCES: AWOS–3 118.325 (507) 359–1656.
COMMUNICATIONS: CTAF/UNICOM 123.0
Ⓡ **MINNEAPOLIS CENTER APP/DEP CON** 127.1
GCO 121.725 (MINNEAPOLIS CENTER and FLIGHT SERVICES)
CLEARANCE DELIVERY PHONE: For CD if una via GCO ctc Minneapolis ARTCC at 651-463-5588.
RADIO AIDS TO NAVIGATION: NOTAM FILE MKT.
MANKATO (L) DME 110.8 MKT Chan 45 N44°13.19′ W93°54.74′ 283° 26.1 NM to fld. 1026.
DME unusable:
325°–150° byd 16 NM



NODINE N43°54.74′ W91°28.05′ NOTAM FILE PNM. **CHICAGO**
(VH) (H) VORTACW 117.9 ODI Chan 126 249° 16.8 NM to Rushford Muni/Robert W Bunke Fld. 1282/1E. **H–2I, L–28F**

NORMAN CO ADA/TWIN VALLEY (See ADA/TWIN VALLEY on page 147)

NORTHOME MUNI (43Y) 2 NE UTC–6(–5DT) N47°53.28′ W94°15.49′ **TWIN CITIES**
1430 B NOTAM FILE PNM
RWY 12–30: 3199X147 (TURF) LIRL(NSTD)
RWY 12: Tree.
RWY 30: Trees.
RWY 02–20: 2049X148 (TURF)
RWY 02: Trees.
RWY 20: Thld dsplcd 209′. Trees.
SERVICE: **LGT** Rwy 12–30 NSTD LIRL due to vrb spacing, nmrs rwy edge lgts inop.
AIRPORT REMARKS: Unattended. Rwy 02–20 not mntnd winter months. Rwy 02 marked with yellow cones. Rwy 20 rwy and dthr mkd with yellow cones. Rwy 12–30 marked with yellow cones. Rwy 02 uneven surface near rwy end. Ruts in Rwy 12–30. Tiedowns not mkd.
AIRPORT MANAGER: 218-434-1743
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.