TWIN MOUNTAIN (8B2) 1 SW UTC–5(–4DT) N44°15.84′ W71°32.80′ **MONTREAL L–32H**
1459 NOTAM FILE BGR
RWY 09–27: H2660X60 (ASPH) S–8.5 LIRL
RWY 09: Trees.
RWY 27: Trees.
AIRPORT REMARKS: Attended irregularly. Nov–Mar unattended. Arpt not plowed in winter. For information call 603–846–5505. Wildlife on and invof arpt. Acft are requested to stay on paved surfaces only. Rwy 09–27 cntr 30 ft of rwy good cond. Outer 15 ft of rwy in fair cond.
AIRPORT MANAGER: 603-325-5470
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
RADIO AIDS TO NAVIGATION: NOTAM FILE MPV.
MONTPELIER (VL) (DH) VORW/DME 116.9 MPV Chan 116 N44°05.13′ W72°26.96′ 090° 40.4 NM to fld. 2086/16W.
VOR unusable:
010°–020° byd 25 NM blo 7,500′
015°–031° byd 40 NM
032°–042° byd 40 NM blo 5,000′
032°–042° byd 65 NM
043°–060° byd 40 NM
043°–070° byd 40 NM blo 9,100′
045°–060° byd 24 NM blo 8,500′
170°–182° byd 40 NM
210°–275° byd 40 NM
DME unusable:
043°–070° byd 40 NM
045°–060° byd 24 NM blo 8,500′

WHITEFIELD

MOUNT WASHINGTON RGNL (HIE)(KHIE) 3 E UTC–5(–4DT) N44°22.05′ W71°32.75′ **MONTREAL L–32H IAP**
1072 B TPA—2072(1000) NOTAM FILE HIE
RWY 10–28: H4001X75 (ASPH) S–30 MIRL 0.6% up E
RWY 10: REIL. PAPI(P4L)—GA 3.5° TCH 45′. Trees.
RWY 28: REIL. Trees. Rgt tfc.
SERVICE: S4 **FUEL** 100LL **LGT** ACTIVATE REIL Rwy 10 and Rwy 28; PAPI Rwy 10; MIRL Rwy 10–28—CTAF.
AIRPORT REMARKS: Attended irregularly. Wildlife on and invof arpt. Arpt conds not rglrly mnt. 100LL self svc avbl 24 hrs with credit card. Cold temperature airport. Altitude correction required at or below –28C. Rwy 28 trans line across apch 20:1+ and marked with day glow balls. Rising trrn lctd 3NM SE of arpt.
AIRPORT MANAGER: 603-837-9532
WEATHER DATA SOURCES: ASOS 118.525 (603) 837–2769.
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ **BOSTON CENTER APP/DEP CON** 135.7
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
RADIO AIDS TO NAVIGATION: NOTAM FILE MPV.
MONTPELIER (VL) (DH) VORW/DME 116.9 MPV Chan 116 N44°05.13′ W72°26.96′ 082° 42.5 NM to fld. 2086/16W.
VOR unusable:
010°–020° byd 25 NM blo 7,500′
015°–031° byd 40 NM
032°–042° byd 40 NM blo 5,000′
032°–042° byd 65 NM
043°–060° byd 40 NM
043°–070° byd 40 NM blo 9,100′
045°–060° byd 24 NM blo 8,500′
170°–182° byd 40 NM
210°–275° byd 40 NM
DME unusable:
043°–070° byd 40 NM
045°–060° byd 24 NM blo 8,500′
MAHN NDB (MHW) 386 GMA N44°21.74′ W71°41.15′ 104° 6.0 NM to fld. 1425/17W. NOTAM FILE HIE. NDB unmonitored.
NDB unusable:
Byd 15 NM blo 9,000′