FORT ANN

HARRIS (83K) 2 W UTC–5(–4DT) N43°24.59′ W73°31.96′ **NEW YORK**
261 NOTAM FILE BTV
RWY 04–22: 2200X50 (TURF) 1.7% up SW
RWY 04: Tree. Rgt tfc.
RWY 22: Tree.
SERVICE: **FUEL** 100LL
AIRPORT REMARKS: Unattended. No flying west of rwy over houses. Upslope at thld Rwy 22.
AIRPORT MANAGER: 518-232-7896
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

FRANCIS S GABRESKI (See WESTHAMPTON BEACH on page 253)

FRANKFORT–HIGHLAND (See UTICA/FRANKFORT on page 249)

FREDERICK DOUGLASS/GREATER ROCHESTER INTL (See ROCHESTER on page 238)

FREEHOLD (1I5) 1 NW UTC–5(–4DT) N42°21.84′ W74°03.90′ **NEW YORK**
440 NOTAM FILE BTV
RWY 12–30: H2275X22 (ASPH) 0.7% up NW
RWY 12: Trees.
RWY 30: Trees.
AIRPORT REMARKS: Attended Apr–Dec 1400Z‡–dusk. Extensive glider activity, especially on weekends. Rwy 12–30 sfc broken and spalling for entire length. Ctc amgr for ficons Dec 1–Apr 1. Rgt tfc for gliders Rwy 12 only. Rwy 12–30 100′ by 2640′ turf rwy adjacent to paved rwy (south edge) beginning at 735′ from Rwy 30 thld.
AIRPORT MANAGER: 518-253-4859
COMMUNICATIONS: CTAF 122.85
CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

FRIKK N40°46.59′ W73°28.95′ NOTAM FILE FRG.
NDB (LOMW) 407 FR 146° 4.2 NM to Republic. 142/14W.