UTICA N43º01.59´ W75º09.87´ NOTAM FILE BUF. **NEW YOUR L–32G**
(L) TACAN 111.2 UCA Chan 49 331º 16.4 NM to Griffiss Intl. 1420/12W.
RCO 122.2 (BUFFALO RADIO)

WALLKILL

KOBELT (N45) 2 NE UTC–5(–4DT) N41º37.45´ W74º08.50´ **NEW YORK**
420 B NOTAM FILE ISP
RWY 03–21: H2864X50 (ASPH) S–13
RWY 03: Trees.
RWY 21: Trees.
AIRPORT REMARKS: Unattended. Arpt clsd to acft 13,500 lbs and over. Deer on and invof arpt. PJE at arpt 3.0 NM radius SFC–14,500´. Rwy 03 has access road 16´ from thld both sides. Rwy center width of 30´ in good condition, 10´ width on both sides of centerline in poor condition with extensive cracks and vegetation. Rwy 03–21 slight depression in grass areas opposite south end of rwy. Rwy center 30´ in fair condition, outside edges beyond this in poor condition. 18´ wide parallel twy, stub connectors to rwy between ends in poor condition.
AIRPORT MANAGER: 914-548-3028
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.

WARWICK MUNI (N72) 3 NE UTC–5(–4DT) N41º17.26´ W74º17.23´ **NEW YORK**
540 NOTAM FILE ISP
RWY 08–26: 2250X80 (TURF)
RWY 08: Tree.
RWY 26: Tree.
RWY 03R–21L: H2150X28 (ASPH) LIRL(NSTD)
RWY 03R: Tree.
RWY 21L: Trees.
RWY 03L–21R: 2100X50 (TURF)
RWY 03L: Trees.
RWY 21R: Trees.
SERVICE: FUEL 100LL **LGT** ACTIVATE LIRL Rwy 03R–21L—CTAF.
AIRPORT REMARKS: Attended irregularly. Arpt CLOSED to tran acft sunset–sunrise. Deer and bird act near movement areas. Mountains and twrs in close vicinity of arpt. Self svc fuel avbl. Rwy 08 has 6´ chain link fence 58´ left, parallel to rwy. Practice ldgs NA. Rwy 03R–21L NSTD LIRL, spacing 400´ apart. Seaplane use of Wickham Lake prohibited.
AIRPORT MANAGER: 845-258-0183
COMMUNICATIONS: CTAF/UNICOM 123.0
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.