
COVE VALLEY (See WILLIAMSBURG on page 314)

CRESCO

ROCKY HILL (48P) 1 SE UTC–5(–4DT) N41°08.91′ W75°16.52′ **NEW YORK**
1240 NOTAM FILE IPT
RWY 09–27: 1000X100 (TURF)
RWY 09: Thld dsplcd 130′. Trees.
RWY 27: Thld dsplcd 80′. Trees.
AIRPORT REMARKS: Unattended. Deer and wildlife on and invof arpt. Announce tfc on—CTAF 122.9.
AIRPORT MANAGER: 570-595-2269
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Allentown Apch at 800-728-6322.

DANVILLE (8N8) 3 SW UTC–5(–4DT) N40°56.90′ W76°38.64′ **NEW YORK**
559 B NOTAM FILE IPT **L–30J**
RWY 09–27: H3000X60 (ASPH) MIRL 0.4% up E **IAP**
RWY 09: Trees.
RWY 27: Trees.
SERVICE: S4 **LGT** Lighting NSTD. ACTVT MIRL Rwy 09–27 drg periods of darkness only—CTAF. Rwy 27 thld lgts dsplcd 365′ from rwy end for ngt displacement. Rwy end lgtd with two red lgts on left side (NSTD).
AIRPORT REMARKS: Attended irregularly. After hrs ctc 570–274–6190. Deer and wildlife on and invof arpt. Radio controlled airplane ops N of rwy. Main ramp no prop wash invof main hangar due to acft painting.
AIRPORT MANAGER: 570-274-6190
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ **WILKES–BARRE APP/DEP CON** 126.3
CLEARANCE DELIVERY PHONE: For CD ctc Wilkes-Barre Apch at 570-655-2084.
RADIO AIDS TO NAVIGATION: NOTAM FILE IPT.
MILTON (L) (L) VORTACW 109.2 MIP Chan 29 N41°01.40′ W76°39.92′ 177° 4.6 NM to fld. 1000/9W.



DECK (See MYERSTOWN on page 291)

DONEGAL SPRINGS AIRPARK (See MOUNT JOY/MARIETTA on page 289)

DOVER

LAZY B RANCH (ØP8) 3 E UTC–5(–4DT) N40°01.47′ W76°48.92′ **NEW YORK**
476 NOTAM FILE IPT
RWY 05–23: H2400X60 (ASPH–CONC) LIRL 1.3% up SW
RWY 23: Trees.
SERVICE: **LGT** For LIRL Rwy 05–23 key 122.9 five times.
AIRPORT REMARKS: Unattended. Ctc arpt manager 717–292–7029. Rwy CLSD dly SS–SR. Deer invof arpt. Rwy 05–23 large patches of conc on edges of rwy with sfc cracking and vegetation growth. Turf area parallel to Rwy 05–23, for taxi only.
AIRPORT MANAGER: 717-577-8827
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.