
GORDONSVILLE MUNI (GVE)(KGVE) 2 NE UTC–5(–4DT) N38°09.36′ W78°09.95′ **WASHINGTON**
452 B NOTAM FILE DCA **L–34E, 36H**
RWY 05–23: H2300X50 (ASPH) S–12.5 MIRL **IAP**
RWY 05: APAP(PNIR). Tree.
RWY 23: APAP(PNIR). Tree.
SERVICE: **LGT** ACTVT MIRL Rwy 05–23—CTAF.
AIRPORT REMARKS: Unattended. After hrs ctc 907–545–4555.
AIRPORT MANAGER: 540-832-2233
WEATHER DATA SOURCES: AWOS–3 120.225 (540) 832–2095.
COMMUNICATIONS: CTAF/UNICOM 123.0
Ⓡ **POTOMAC APP/DEP CON** 132.85
CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-640-4124.
RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.
(VH) (H) VORTACW 115.6 GVE Chan 103 N38°00.82′ W78°09.18′ 002° 8.6 NM to fld. 383/6W.
TACAN AZIMUTH unusable:
250°–260° byd 25 NM blo 7,000′
VOR unusable:
005°–050° byd 40 NM
180°–207° byd 40 NM
208°–218° byd 40 NM blo 3,000′
208°–218° byd 50 NM
219°–225° byd 40 NM
260°–301° byd 40 NM
302°–312° byd 40 NM blo 9,000′
302°–312° byd 65 NM
313°–331° byd 40 NM
332°–342° byd 40 NM blo 6,100′
332°–342° byd 46 NM
343°–360° byd 40 NM



GORDONSVILLE N38°00.82′ W78°09.18′ NOTAM FILE DCA. **WASHINGTON**
(VH) (H) VORTACW 115.6 GVE Chan 103 002° 8.6 NM to Gordonsville Muni. 383/6W. **H–10H, 12H, L–34E, 36H**
TACAN AZIMUTH unusable:
250°–260° byd 25 NM blo 7,000′
VOR unusable:
005°–050° byd 40 NM
180°–207° byd 40 NM
208°–218° byd 40 NM blo 3,000′
208°–218° byd 50 NM
219°–225° byd 40 NM
260°–301° byd 40 NM
302°–312° byd 40 NM blo 9,000′
302°–312° byd 65 NM
313°–331° byd 40 NM
332°–342° byd 40 NM blo 6,100′
332°–342° byd 46 NM
343°–360° byd 40 NM

HAMPTON ROADS EXEC (See NORFOLK on page 365)

HANOVER CO MUNI (See RICHMOND/ASHLAND on page 374)

HARCUM N37°26.92′ W76°42.68′ NOTAM FILE DCA. **WASHINGTON**
(L) (L) VORTACW 108.8 HCM Chan 25 338° 5.0 NM to Middle Peninsula Rgnl. 8/7W. **H–10H, 12H, L–34E, 36H**
VOR unusable:
056°–095° blo 2,000′
096°–112° byd 20 NM
174°
275°–300° blo 2,000′