CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE BOI.
BOISE (VH) (H) VORTACW 113.3 BOI Chan 80 N43º33.17´ W116º11.53´ 303º 23.5 NM to fld. 2877/17E.
VOR unusable:
001º–044º byd 22 NM blo 11,000´
001º–044º byd 32 NM blo 14,500´
023º–033º byd 40 NM blo 15,500´
023º–033º byd 50 NM blo 18,000´
034º–081º byd 40 NM
045º–071º byd 32 NM blo 12,500´
072º–084º byd 32 NM blo 10,500´
082º–092º byd 40 NM blo 11,500´
082º–092º byd 53 NM blo 14,000´
082º–092º byd 71 NM blo 18,000´
093º–107º byd 40 NM
108º–118º byd 40 NM blo 9,500´
108º–118º byd 56 NM
119º–210º byd 40 NM
211º–221º byd 40 NM blo 9,400´
211º–221º byd 52 NM
222º–233º byd 40 NM
273º–283º byd 40 NM blo 6,000´
273º–283º byd 69 NM blo 9,000´
273º–283º byd 88 NM
284º–295º byd 40 NM
TACAN AZIMUTH unusable:
010º–060º byd 12 NM blo 13,000´
010º–060º byd 27 NM blo 15,500´
113º–155º byd 30 NM blo 7,000´
348º–010º byd 20 NM blo 13,000´
348º–010º byd 27 NM blo 15,500´
DME unusable:
010º–060º byd 12 NM blo 13,000´
010º–060º byd 27 NM blo 15,500´
113º–155º byd 30 NM blo 7,000´
348º–010º byd 20 NM blo 13,000´
348º–010º byd 27 NM blo 15,500´
VOR unusable:
296º–309º byd 40 NM blo 5,500´
296º–309º byd 46 NM blo 9,000´
296º–309º byd 84 NM blo 18,000´
315º–022º byd 40 NM

FAIRFIELD

FROSTENSON FLD (U86) 0 S UTC–7(–6DT) N43º20.51´ W114º47.90´ **SALT LAKE CITY**
5058 NOTAM FILE BOI
RWY 08–26: 2950X40 (DIRT)
RWY 08: Road. Rgt tfc.
RWY 26: Pole.
AIRPORT REMARKS: Unattended. Irregular winter maintenance and snow removal, check rwy condition before using.
AIRPORT MANAGER: (208) 720-9020
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

FISH LAKE (USFS) (S92) 0 E UTC–8(–7DT) N46º19.81´ W115º03.79´ **GREAT FALLS**
5646 NOTAM FILE BOI
RWY 05–23: 2650X50 (TURF)
RWY 05: Tree.
RWY 23: Trees.
AIRPORT REMARKS: Unattended. No winter maintenance. Rwy 05–23 soft when wet. Elk wallows on rwy. Land Rwy 23, tkf Rwy 05. No touch and go ldgs or stop and go ldgs, go arounds not recommended due to steep rising terrain off west end of Rwy 05–23. Rwy 05–23 additional 400´ of length avbl for tkf on the end of Rwy 05. Down drafts prevalent over lake. Ctc USFS arpt manager 208–983–9677 for briefings and rwy conditions. Recommend early morning and late evening ops during summer months. Normally mowed to a usable width of 50´–75´. Rwy 23 end marked with concrete T marker and large w cones. Rwy 05 end marked with large w cones. No telephone avbl at arpt.
AIRPORT MANAGER: 208-983-9677
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.