HILO INTL (ITO)(PHTO) 2 E UTC–10 N19º43.22´ W155º02.91´ HAWAIIAN ISLANDS
38 B LRA ARFF Index—See Remarks NOTAM FILE ITO P–1C, 2H
RWY 08–26: H9803X150 (ASPH–GRVD) S–99, D–154, 2D–275 PCR 390 F/B/X/T HIRL IAP
RWY 08: ODALS. PAPI(P4R)—GA 3.0º TCH 71´. Tree.
RWY 26: MALSR. PAPI(P4L)—GA 2.6º TCH 70´. Tree.
RWY 03–21: H5601X150 (ASPH–GRVD) S–52, D–83, 2D–148 PCR 180 F/B/X/T MIRL
RWY 03: REIL. VASI(V4L)—GA 3.25º TCH 48´. Thld dsplcd 351´. Fence.
RWY 21: Pole.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 03: TORA–5192 TODA–5192 ASDA–5601 LDA–5250
RWY 08: TORA–9803 TODA–9803 ASDA–9803 LDA–9803
RWY 21: TORA–5250 TODA–5250 ASDA–5510 LDA–5510
RWY 26: TORA–9803 TODA–9803 ASDA–9803 LDA–9803
SERVICE: S1 **FUEL** 100LL, JET A, A+, MOGAS **LGT** ACTIVATE MIRL Rwy 3–21, HIRL Rwy 08–26, MALSR Rwy 26 and ODALS Rwy 08–118.1. Rwy 08 PAPI unusable byd 3 NM.
NOISE: Avoid overflight of noise sensitive residential areas north, west and southwest of arpt.
AIRPORT REMARKS: Attended 1700–0630Z. Be alert–occasional bird flocks on arpt and in flight across Rwy 08–26 and Rwy 03–21. Twy E btn Twy A and Rwy 08–26 ponding drg hvy rains. For fuel advance notice required, for 100LL call 808 960–5146 or ctc freq 128.95, for JET A call 808–934–7757 or ctc freq 130.8. Class I, ARFF Index C. ARFF avbl 24 hrs, contact 118.1 or 808–961–9317. The 1325´ paved area at approach end Rwy 08 marked by chevrons not usable for landing, takeoff, overrun or stopway and cannot be used in computing takeoff data for Rwy 08–26. Obstruction lighted 181´ smoke stack located 1/2 mile south of field. Rwys 08, 21 and 26 wind cones are lctd in the ROFA. Tower controls entry/exit traffic on taxiways F and E to east terminal ramp. Division 1.1, 1.2, 1.3 explosives prohibited. PPR from arpt manager for transportation of Division 1.4 explosives and hazardous material in or out of arpt. PPR from arpt manager for transient parking. SAID in use. Operate transponders with altitude reporting mode and ADS–B (if equipped) enabled on all airport surfaces. Customs available. Jet fuel available Mon–Sat 1800–0300Z call 808 935–6881/6122 or 961–6601. No mkd pad, hel oper fm FBO hanger area. NOTE: See Area Notices—General Information On Flying To Hawaii.
AIRPORT MANAGER: 808-961-9300
WEATHER DATA SOURCES: ASOS (808) 825–4702
COMMUNICATIONS: CTAF 118.1 **ATIS** 126.4
Ⓡ **HILO APP/DEP CON** 119.7 (1600–0800Z)
Ⓡ **HCF APPROACH APP/DEP CON** 118.45 (0800–1600Z) 284.6
TOWER 118.1 (1600–0800Z) **GND CON** 121.9 **CLNC DEL** 120.25
CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Honolulu Control Facility at 808-840-6262.
AIRSPACE: CLASS D svc 1600–0800Z; other times CLASS E.
RADIO AIDS TO NAVIGATION: NOTAM FILE ITO.
(H) (H) VORTACW 116.9 ITO Chan 116 N19º43.28´ W155º00.66´ 257º 2.1 NM to fld. 23/11E.
ILS/DME 110.7 I–ITO Chan 44 Rwy 26. Class IA. Unmonitored when ATCT clsd.

KAMUELA N19º59.88´ W155º40.19´ NOTAM FILE MUE. HAWAIIAN–MARIANA
(H) (H) VORW/DME 113.3 MUE Chan 80 2670/11E. P–2H
VOR portion unusable:
001º–030º byd 10 NM blo 6,000´
070º–084º byd 25 NM blo 7,000´
070º–084º byd 35 NM blo 13,000´
085º–210º byd 15 NM blo 15,500´
290º–360º byd 10 NM blo 7,500´
290º–360º byd 20 NM blo 16,000´
DME unusable:
070º–084º byd 25 NM blo 7,000´
070º–084º byd 35 NM blo 13,000´
085º–210º byd 15 NM blo 15,500´
290º–030º byd 10 NM

PAHOA N19º32.47´ W154º58.33´ NOTAM FILE ITO. HAWAIIAN–MARIANA
NDB (HW) 332 POA 495/11E. NDB unmonitored when ATCT closed. P–2H