TALIHINA MUNI (6F1) 3 SW UTC–6(–5DT) N34º42.47´ W95º04.43´ **DALLAS–FT WORTH**
687 B NOTAM FILE MLC **L–17D**

RWY 01–19: H3300X60 (ASPH) S–12 MIRL
RWY 19: Trees.
SERVICE: **LGT** Actvt MIRL Rwy 01–19—CTAF. Actvt WDI lights–CTAF.
AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: (918) 413-2088
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.
RADIO AIDS TO NAVIGATION: NOTAM FILE MLC.
RICH MOUNTAIN (VL) (L) VORTACW 113.5 PGO Chan 82
N34º40.83´ W94º36.54´ 270º 23.1 NM to fld. 2700/4E.
VOR unusable:
016º–021º byd 40 NM
028º–029º byd 40 NM
030º–040º
050º–075º blo 4,000´
090º–145º
167º–169º byd 40 NM
170º–200º
235º–245º byd 30 NM blo 5,000´
260º–280º byd 35 NM blo 5,000´
329º–335º byd 40 NM
340º–345º blo 5,000´
358º–002º byd 40 NM



TENKILLER LAKE AIRPARK (See COOKSON on page 194)

TEXHOMA MUNI (K49) 1 W UTC–6(–5DT) N36º30.34´ W101º48.82´ **WICHITA**
3468 NOTAM FILE MLC **L–15B**

RWY 03–21: H3564X48 (ASPH) MIRL
RWY 03: Thld dsplcd 590´. Road.
RWY 21: Thld dsplcd 340´. Fence.
RWY 17–35: 2340X75 (TURF)
RWY 17: Fence.
RWY 35: Road.
SERVICE: **FUEL** 100LL **LGT** ACTVT MIRL RWY 03–21—CTAF. RWY 03–21 MIRL OTS INDEF.
AIRPORT REMARKS: Unattended. Ultralight activity on and invof arpt. For fuel call 580–522–2009. Rwy 03–21 not mkd. Wind turbines 350 ft AGL lctd 2 mi south of arpt.
AIRPORT MANAGER: 806-753-6567
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.
RADIO AIDS TO NAVIGATION: NOTAM FILE DHT.
DALHART (L) (L) VORTACW 112.0 DHT Chan 57 N36º05.49´
W102º32.68´ 043º 43.3 NM to fld. 4020/12E.
TAC AZM unusable:
240º–255º byd 15 NM
320º–350º byd 15 NM



TEXOMA N33º56.65´ W96º23.51´ NOTAM FILE DUA. **DALLAS–FT. WORTH**
(L) DME 114.3 URH Chan 90 at Durant Rgnl/Eaker Fld. 682. **H–6H, L–17D**
DME unusable:
207º–240º byd 35 NM blo 2,500´
335º–350º byd 35 NM blo 2,500´