HERITAGE CREEK AIRSTRIP (58T) 9 SE UTC–6(–5DT) N33º09.96´ W97º28.79´ **DALLAS–FT WORTH COPTER**
883 NOTAM FILE FTW
RWY 13–31: 3000X60 (TURF) LIRL 0.8% up NW
RWY 13: Tree.
RWY 31: Tree. Rgt tfc.
SERVICE: S4 **LGT** ACTVT LIRL Rwy 13–31 —CTAF. Rwy defined by white "L" markers on each corner—nights: two lights each side of cntrln mark rwy ends.
AIRPORT REMARKS: Unattended. Deer and birds on and invof arpt. Parachute activity invof arpt. Remote controlled acft ops on arpt. All acft monitor CTAF due to the close proximity of Rhome Meadows arpt. Rwy 31 right tfc for fixed wing acft only; remain east of the rwy.
AIRPORT MANAGER: (817) 988-9745
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

LAZY G BAR RANCH (Ø9T) 5 NE UTC–6(–5DT) N33º16.88´ W97º29.80´ **DALLAS–FT WORTH**
931 NOTAM FILE FTW
RWY 17–35: 1600X40 (TURF–DIRT)
RWY 17: Brush. Rgt tfc.
AIRPORT REMARKS: Unattended. Livestock on and invof arpt. For fld condition call arpt manager. Call ahead to confirm rwy is clear of livestock. Rough, rolling gradient. Full rwy not visible from ends. Center 20´ mowed.
AIRPORT MANAGER: (719) 221-7993
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.

TRIPLE–ACE FLD (35X) 2 NE UTC–6(–5DT) N33º15.11´ W97º33.21´ **DALLAS–FT WORTH**
1010 NOTAM FILE 35X
RWY 02–20: 1271X40 (TURF)
RWY 02: Road. Rgt tfc.
RWY 20: Fence.
AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Acft oprg into or out of arpt will use Decatur Arpt freq 122.8 to communicate with Decatur Arpt tfc. Rwy soft aft rain. Call for ficons.
AIRPORT MANAGER: 940-627-6800
COMMUNICATIONS: CTAF 122.8