TEXICO N34°29.71′ W102°50.38′ NOTAM FILE FTW. ALBUQUERQUE
(VH) (H) VORTACW 112.2 TXO Chan 59 240° 12.5 NM to Clovis Rgnl. 4060/11E. H–6G, L–6H
VOR unusable:
095°–100° byd 40 NM
120°–130° byd 40 NM
210°–272° byd 60 NM blo 10,000′
273°–283° byd 40 NM blo 6,000′
273°–283° byd 46 NM blo 7,000′
273°–283° byd 59 NM
284°–319° byd 40 NM
320°–035° byd 40 NM
TACAN AZIMUTH unusable:
222°–232°

THREE RIVERS N28°30.30′ W98°09.03′ NOTAM FILE SJT. SAN ANTONIO
(L) TACAN 111.4 THX Chan 51 160° 8.7 NM to Live Oak Co. 266/8E. H–7B, L–20H

THROCKMORTON MUNI (72F) 1 NE UTC–6(–5DT) N33°10.80′ W99°08.99′ DALLAS–FT WORTH
1273 B NOTAM FILE FTW L–17B
RWY 17–35: H3723X60 (ASPH) S–12 LIRL
RWY 17: Road.
RWY 35: Trees.
SERVICE: **LGT** Rwy 17 has nonstd dsplcd thr lgts. Rwy 35 does not have dsplcd thr lights. Rwy lts obscured by vegetation. Opr sts unkn.
AIRPORT REMARKS: Unattended. Rwy 17–35 Nmrs conc & asph patches with cracks and loose grvl. Rwy uneven due to extsv patching. Rwy 17 and Rwy 35 rwy mkg poor.
AIRPORT MANAGER: 940-849-4411
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.
RADIO AIDS TO NAVIGATION: NOTAM FILE SPS.
WICHITA FALLS (VH) (H) VORTACW 112.7 SPS Chan 74 N33°59.24′ W98°35.61′ 200° 55.8 NM to fld. 1133/10E.

TRADEWIND (See AMARILLO on page 265)

TRINITY N29°32.78′ W94°44.85′ NOTAM FILE CXO. HOUSTON
(VL) (DL) VORW/DME 114.75 MHF Chan 94(Y) 011° 14.1 NM to Chambers Co. 38/7E. H–7C, L–19E, 21A, GOAW
VOR unusable:
060°–079° byd 40 NM
080°–090° byd 40 NM blo 6,000′
080°–090° byd 50 NM blo 8,000′
091°–109° byd 40 NM
110°–190° blo 2,000′

TRIPLE–ACE FLD (See DECATUR on page 312)

TRUAX N27°41.18′ W97°17.68′ NOTAM FILE NGP. BROWNSVILLE
(L) TACAN 114.0 NGP Chan 87 at Corpus Christi NAS (Truax Fld). 17/3E. L–20H, 21A, GOAW
No NOTAM MP: 1500–1800Z‡ 2nd Wed ea Month
DME unusable:
190°–305° byd 20 NM blo 2,000′
333°–343° byd 10 NM blo 8,000′

TSTC WACO (See WACO on page 455)