BASTROP

MOREHOUSE MEML (BQP)(KBQP) 2 SE UTC–6(–5DT) N32°45.37′ W91°52.84′ **MEMPHIS**
168 B TPA—1201(1033) NOTAM FILE DRI **L–18F**
RWY 16–34: H4002X100 (ASPH) S–15.5 MIRL **IAP**
RWY 16: REIL. PAPI(P2L)—GA 3.0° TCH 50′.
RWY 34: REIL. PAPI(P2L)—GA 3.0° TCH 50′.
SERVICE: S2 **FUEL** 100LL **LGT** Dusk–Dawn. REIL Rwys 16 and 34; MIRL Rwy 16–34 preset low intst dusk–dawn, to incr intst ACTVT—CTAF. PAPI Rwy 16 OTS indef. Rwy 34 REIL OTS indefly.
AIRPORT REMARKS: Attended Mon–Fri 1315–2100Z‡. Deer on and invof rwy. Self serve fuel avbl 24 hrs with credit card. Rwy 16 mkgs in poor cond due to fading and mold growth. Rwy 34 cracking, fading, and mold growth on rwy mkgs. Ctc aprt mgr for dsgnd ramp space for pub use.
AIRPORT MANAGER: 318-281-2018
WEATHER DATA SOURCES: AWOS–3PT 118.375 (318) 281–1443. Wind unrel.
COMMUNICATIONS: CTAF/UNICOM 122.8
Ⓡ **MONROE APP/DEP CON** 126.9 (1200–0400Z‡)
Ⓡ **FORT WORTH CENTER APP/DEP CON** 126.325 (0400–1200Z‡)
CLEARANCE DELIVERY PHONE: For CD ctc Monroe Apch at 318-327-5641, if unavbl, ctc Fort Worth ARTCC at 817-858-7584.
RADIO AIDS TO NAVIGATION: NOTAM FILE MLU.
MONROE (VL) (L) VORTACW 117.2 MLU Chan 119 N32°31.01′ W92°02.16′ 026° 16.3 NM to fld. 77/3E.
VOR unusable:
010°–040° byd 40 NM
125°–135° byd 40 NM
215°–231° byd 40 NM
232°–242° byd 40 NM blo 8,000′
232°–242° byd 83 NM
243°–255° byd 40 NM blo 7,000′
243°–255° byd 56 NM
256°–267° byd 40 NM blo 18,000′
256°–267° byd 45 NM
268°–271° byd 40 NM
272°–282° byd 40 NM blo 2,000′
272°–282° byd 51 NM
283°–315° byd 40 NM
345°–355° byd 40 NM
DME unusable:
097°–131° blo 3,000′
097°–131° byd 20 NM
TACAN AZIMUTH unusable:
097°–131° blo 3,000′
097°–131° byd 20 NM
BASTROP NDB (MHW) 329 BQP N32°45.28′ W91°53.01′ at fld. 159/3E. NOTAM FILE DRI.
AWOS broadcasted on NDB

