JACKSONVILLE

ALBERT J ELLIS (OAJ)(KOAJ) 10 NW UTC–5(–4DT) N34°49.75′ W77°36.73′ **CHARLOTTE**
93 B ARFF Index—See Remarks NOTAM FILE OAJ **H–9C, 12H, L–35B**
RWY 05–23: H7100X150 (ASPH–GRVD) S–120, D–250, 2S–175, 2D–498 PCR 590 F/A/W/T HIRL **IAP, AD**
RWY 05: MALSR. PAPI(P4L)—GA 3.0° TCH 55′.
RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 47′.
SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTVT MALSR Rwy 05; REIL Rwy 23; PAPI Rwy 05 and 23; HIRL Rwy 05–23—CTAF.
AIRPORT REMARKS: Attended 1000–0500Z‡. For fuel other hrs call 910–347–8366. Class I, ARFF Index B. Clsd to unsked ACR opns with more than 30 psgr seats excp PPR call amgr 910–324–1100 or 910–989–3168. Index B ARFF coverage provided during commercial air trc ops. Index C available upon req. Clsd to all mil acft over 17,000 lbs for air carrier ramp ops exc 24 hr PPR. Call arpt mgr 910–324–1100 or 910–989–3168. 180° turns on Rwy 05–23 not authorized for acft 60,000 lbs and over. Field conditions not monitored 0500–1000Z‡ daily.
AIRPORT MANAGER: 910-324-1100
WEATHER DATA SOURCES: AWOS–3PT (910) 324–5233 LAWRS.
COMMUNICATIONS: CTAF 132.65 **UNICOM** 122.95 **ATIS** 124.475 or call 910–324–5233
Ⓡ **WILMINGTON APP/DEP CON** 135.75 (1100–0400Z‡)
Ⓡ **WASHINGTON CENTER APP/DEP CON** 124.025 135.75 (0400–1100Z‡)
ELLIS TOWER 132.65 (1200–0300Z‡)
GND CON 125.4 **CLNC DEL** 125.4 **CLNC DEL** 121.4 (When twr clsd)
CLEARANCE DELIVERY PHONE: For CD when ATCT clsd, ctc Wilmington Apch at 910-815-4676, or when Apch clsd ctc Washington ARTCC at 703-771-3587.
AIRSPACE: CLASS D svc 1200–0300Z‡; other times CLASS E.
RADIO AIDS TO NAVIGATION: NOTAM FILE ILM.
WILMINGTON (H) (H) VORTACW 117.0 ILM Chan 117 N34°21.10′ W77°52.46′ 031° 31.4 NM to fld. 29/7W.
VOR portion unusable:
051°–185°
164°–051° blo 17,500′
186°–229° blo 3,000′
230°–315° byd 5 NM blo 17,500′
316°–050° blo 8,000′
TACAN DME unusable:
015°–305° byd 30 NM blo 2,500′
TACAN AZIMUTH unusable:
129°–160° byd 30 NM blo 2,500′
ELLAS NDB (LOMW) 261 OA N34°45.03′ W77°42.27′ 052° 6.6 NM to fld. 76/8W. NOTAM FILE OAJ.
ILS/DME 108.7 I–OAJ Chan 24 Rwy 05. Class IA. LOM ELLAS NDB. LOM ELLAS NDB unmonitored. LOC unusable byd 15° right of course. Autopilot cpd apch NA blw 900′ MSL.

SKY MANOR (N22) 8 W UTC–5(–4DT) N34°42.65′ W77°35.10′ **CHARLOTTE**
60 NOTAM FILE RDU
RWY 08–26: 3610X85 (TURF)
RWY 08: Thld dsplcd 595′. Trees.
RWY 26: Trees.
AIRPORT REMARKS: Unattended. Be alert deer invof arpt. Arpt is being reconstructed; men and eqpt on and invof Rwy 08–26. Rwy 08–26 has no markings due to ongoing reconstruction. Pvt road parls rwy on S side 20′ from rwy edge.
AIRPORT MANAGER: 910-389-3014
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.