MOCKSVILLE

TWIN LAKES (8A7) 5 NE UTC–5(–4DT) N35°54.89′ W80°27.41′ **CHARLOTTE**
818 B NOTAM FILE RDU **L–25D, 36F**
RWY 09–27: H2943X50 (ASPH) S–12.5 RWY LGTS(NSTD) **IAP**
1.5% up E
RWY 09: PAPI(P2L)—GA 3.5° TCH 49′. Trees.
RWY 27: Trees.
SERVICE: S4 **FUEL** 100LL **OX** 4 **LGT** Rwy 09–27 nstd lighting due to number and location.
AIRPORT REMARKS: Attended 1300–2200Z‡. Deer/migratory birds occasionally on arpt. For after hrs svc ctc 336–998–2126. 100LL 24 hr self service with credit card. Rwy 09 18′ drop–off 150′ from thld left and right of centerline. Rwy 09 uphill grade. Rwy 09–27 markings nonstandard due to size and location.
AIRPORT MANAGER: 336-998-8101
COMMUNICATIONS: CTAF/UNICOM 122.7
Ⓡ **GREENSBORO APP/DEP CON** 124.35
CLEARANCE DELIVERY PHONE: For CD ctc Greensboro Apch at 336-333-5119.
RADIO AIDS TO NAVIGATION: NOTAM FILE GSO.
GREENSBORO (VH) (H) VORTACW 116.2 GSO Chan 109 N36°02.74′ W79°58.58′ 255° 24.7 NM to fld. 908/3W.
TACAN AZIMUTH unusable:
255°–290° byd 10 NM blo 6,000′
VOR unusable:
010°–015° byd 40 NM
072°–076° byd 40 NM
083°–093° byd 40 NM blo 6,000′
083°–093° byd 93 NM
107°–111° byd 40 NM
118°–156° byd 40 NM
157°–167° byd 40 NM blo 3,600′
157°–167° byd 48 NM
168°–180° byd 40 NM
196°–199° byd 40 NM
240°–250° byd 40 NM
260°–276° byd 40 NM
277°–288° byd 40 NM blo 3,500′
277°–288° byd 47 NM blo 6,000′
277°–288° byd 56 NM
289°–302° byd 40 NM blo 5,000′
289°–302° byd 55 NM
303°–317° byd 40 NM blo 5,200′
303°–317° byd 55 NM
318°–354° byd 40 NM

