HESPERIA (L26) 3 S UTC–8(–7DT) N34º22.62´ W117º18.96´ **LOS ANGELES**
3390 B NOTAM FILE RAL **L–4H, 7C**
RWY 03–21: H3910X50 (ASPH) S–12 LIRL 0.5% up SW
RWY 03: Thld dsplcd 300´. Tree. Rgt tfc.
RWY 21: Thld dsplcd 550´. Road.
SERVICE: **FUEL** 100LL **LGT** ACTIVATE LIRL Rwy 03–21—CTAF.
AIRPORT REMARKS: Unattended. Slight uphill grade to Rwy 21. Pilots should be aware of rising surrounding terrain to the south. Rwy 21 has a perimeter fence that separates Rwy 21 from road. Public road access to rwy and twy in multiple locations. Calm wind use Rwy 21.
AIRPORT MANAGER: (442) 243-4331
COMMUNICATIONS: CTAF/UNICOM 123.0
CLEARANCE DELIVERY PHONE: For CD ctc Joshua Apch at 661-277-3843.
RADIO AIDS TO NAVIGATION: NOTAM FILE RAL.
PARADISE (H) VORTAC 112.2 PDZ Chan 59 N33º55.10´ W117º31.80´ 006º 29.5 NM to fld. 1432/15E.
TACAN AZIMUTH unusable:
130º–145º byd 25 NM blo 5,000´
145º–190º blo 8,000´
190º–230º blo 10,000´
310º–325º byd 35 NM blo 10,900´
325º–345º byd 25 NM blo 11,500´
345º–360º byd 35 NM blo 10,500´
VOR unusable:
010º–015º byd 20 NM blo 10,000´
130º–145º byd 25 NM blo 5,000´
145º–190º blo 8,000´
145º–190º byd 25 NM blo 10,000´
145º–190º byd 39 NM blo 13,500´
190º–230º blo 10,000´
310º–325º byd 35 NM blo 10,900´
325º–345º byd 25 NM blo 11,500´
345º–360º byd 35 NM blo 10,500´
DME unusable:
130º–145º byd 25 NM blo 5,000´
145º–190º blo 8,000´
190º–230º blo 10,000´
310º–325º byd 35 NM blo 10,900´
325º–345º byd 25 NM blo 11,500´
345º–360º byd 35 NM blo 10,500´

HOLLISTER

FRAZIER LAKE AIRPARK (1C9) 8 NW UTC–8(–7DT) N36º57.17´ W121º27.76´ **SAN FRANCISCO**
152 NOTAM FILE OAK
RWY 05–23: 2500X100 (TURF) LIRL
RWY 05: P–line.
RWY 23: REIL. Rgt tfc.
SERVICE: **LGT** ACTIVATE REIL Rwy 23; LIRL Rwy 05–23—CTAF. Rwy 23 REIL opr consistently during daylt hours. During ngt hrs ACTIVATE REIL Rwy 23—CTAF 7 clicks.
AIRPORT REMARKS: Unattended. No touch and go ops. Birds frequently on and invof arpt. Wildlife haz near movement area. Use at your own risk. Rwy 05–23 irregular sfc. Be alert to seaplane ldg area (water channel) 200´ south of adjacent/parallel grass rwy. Berm and ditch adjacent to Rwy 05 apch end. PAEW in vicinity of Rwy 05–23 occasionally during dalgt hrs. Rwy clsd by NOTAM for mowing, typically Mon. Equipment on rwy duing mowing ops. Utility wires across west end of afld for apch to Rwy 05 and waterway 5W. Occasional irrigation on turf rwy at night from midnight to 1400Z‡. No midfield tkfs or back–taxi on Rwy 05–23. No practice tkf and ldg Rwy 05–23 when wet or soft. Rwy 05–23 gross weight ltd to 6,700 pounds.
AIRPORT MANAGER: (408) 242-8873
COMMUNICATIONS: CTAF/UNICOM 123.05
CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-3748.

• • • • • • • • • • • • • • • • • •

WATERWAY 05W–23W: 3000X60 (WATER)
WATERWAY 05W: P–line.
WATERWAY 23W: Rgt tfc.
SEAPLANE REMARKS: Waterway 05–23 not marked, typical water depth 2.5´. Water depth noted as shallow as 1 1/2´ deep. Ramp & dock facilities avbl.