MARKLEEVILLE

ALPINE CO (M45) 3 N UTC–8(–7DT) N38°44.09′ W119°46.02′ **SAN FRANCISCO L–9A**

5872 TPA—6672(800) NOTAM FILE RNO

RWY 17–35: H4443X50 (ASPH) 1.0% up S

RWY 17: Hill.

RWY 35: Rgt tfc.

AIRPORT REMARKS: Unattended. No snow removal, arpt CLOSED when snow on rwy. Soil conditions off rwy is poor in wet conditions. Call public works for additional information 530–694–2140 extension O. Large stones along edge of rwy off graded surface. Rwy 17–35 ltd by arpt opr to 4,800 lbs single wheel, 9,600 lbs dual wheel. Rwy 17–35 loose grvl on rwy.

AIRPORT MANAGER: 530-694-2140

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.

MUSTANG (VH) (H) VORTACW 117.9 FMG Chan 126 N39°31.88′ W119°39.36′ 170° 48.0 NM to fld. 5950/16E.

VOR unusable:
- 002°–012° byd 40 NM blo 19,000′
- 013°–022° byd 40 NM blo 10,300′
- 013°–022° byd 53 NM
- 023°–045° byd 40 NM
- 079°–113° byd 40 NM
- 114°–124° byd 40 NM blo 10,000′
- 114°–124° byd 52 NM
- 125°–145° byd 40 NM
- 153°–172° byd 40 NM blo 15,000′
- 153°–172° byd 52 NM blo 18,000′
- 173°–186° byd 40 NM
- 187°–197° byd 40 NM blo 15,000′
- 187°–197° byd 66 NM
- 198°–212° byd 40 NM
- 200°–230° byd 30 NM blo 13,000′
- 213°–223° byd 40 NM blo 18,000′
- 224°–304° byd 40 NM
- 327°–339° byd 40 NM blo 14,000′
- 356°–001° byd 40 NM

TACAN AZIMUTH unusable:
- 200°–230° byd 30 NM blo 13,000′

DME unusable:
- 200°–230° byd 30 NM blo 13,000′