
WILLOWS/GLENN CO (WLW)(KWLW) 1 W UTC–8(–7DT) N39°30.95′ W122°13.04′ **SAN FRANCISCO L–2G IAP**
141 B NOTAM FILE RIU
RWY 16–34: H4125X100 (ASPH) S–38, D–53 MIRL
RWY 16: Road. Rgt tfc.
RWY 34: VASI(V4L)—GA 3.0° TCH 31′.
RWY 13–31: H3788X60 (ASPH) S–12
RWY 13: Trees. Rgt tfc.
RWY 31: Thld dsplcd 243′.
SERVICE: **FUEL** 100LL **LGT** ACTVT MIRL Rwy 16–34 and VASI Rwy 34—CTAF.
AIRPORT REMARKS: Attended 1530–2330Z‡. 100LL Fuel 24 hr card lock. Ofc at Willows arpt phone 530–624–0836. Rwy 13–31 mrkgs are faded and sfc has alligator cracking. Lndg fee: refer to arpt website for fee schedule.
AIRPORT MANAGER: 530-934-6530
COMMUNICATIONS: **CTAF/UNICOM** 122.8
Ⓡ **OAKLAND CENTER APP/DEP CON** 132.2
CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.



WOODLAKE (042) 2 S UTC–8(–7DT) N36°23.93′ W119°06.41′ **SAN FRANCISCO**
425 B TPA—1225(800) NOTAM FILE RIU
RWY 07–25: H2203X50 (ASPH–TRTD)
RWY 07: Trees.
RWY 25: Bldg.
SERVICE: **FUEL** 100LL
AIRPORT REMARKS: Unattended. Arpt not approved for ngt use. Gross pavement strength provided by arpt manager, 8000 lbs.
AIRPORT MANAGER: 559-564-8055
COMMUNICATIONS: **CTAF** 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.