WALDEN–JACKSON CO (33V) 1 NE UTC–7(–6DT) N40°45.02′ W106°16.29′ **CHEYENNE**
8154 B NOTAM FILE DEN **H–3F, 5A, L–9E, 11E**
RWY 04–22: H5900X75 (ASPH) S–25 MIRL **IAP**
RWY 04: PAPI(P4L)—GA 3.0° TCH 35′.
RWY 22: PAPI(P4L)—GA 3.0° TCH 35′.
RWY 17–35: 4020X100 (TURF) 0.4% up S
RWY 17: Fence.
RWY 35: Road.
SERVICE: **LGT** ACTVT PAPI Rwy 04 and 22; MIRL Rwy 04–22—CTAF.
AIRPORT REMARKS: Attended on call—amgr or 970–723–4481 or 970–846–6971. Rdo ctl model acft ops SE corner of arpt; deer and antelope on rwys. Rwy 04–22 asph pvmt usbl but cracked thrut and delaminating at apch ends. Rwy 04 has +20 ft pline 660 ft fm rwy end 750 ft L of cntrln; 50 ft dropoff 450 ft fm thr. Rwy 17 marked with orange cones. Rwy 35 marked with orange cones. Rwy 17 6 ft pole 100 ft fm thr 10 ft L of rwy edge. Rwy 35 +38 ft trees 300 ft fm thr 154 ft R of apch end; +4 ft fence at thr L & R; fence posts mkd with worn & faded yellow paint; road 24 ft fm thr. Rwy 17–35 sfc very course with animal burrows and vegetation throughout.
AIRPORT MANAGER: 970-723-4660
WEATHER DATA SOURCES: AWOS–3 118.625 (970) 723–4513.
COMMUNICATIONS: CTAF 122.9
Ⓡ **DENVER CENTER APP/DEP CON** 126.5
CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.
KREMMLING (VH) (DH) VORW/DME 113.8 RLG Chan 85 N40°00.16′ W106°26.55′ 356° 45.5 NM to fld. 9415/14E.
DME unusable:
285°–305° byd 34 NM blo 16,300′
VOR unusable:
040°–050° byd 40 NM blo 16,000′
040°–050° byd 55 NM
051°–061° byd 40 NM
062°–072° byd 40 NM blo 15,600′
062°–072° byd 64 NM
073°–085° byd 40 NM blo 15,000′
073°–085° byd 48 NM
086°–119° byd 40 NM
120°–130° byd 40 NM blo 16,500′
120°–130° byd 62 NM
131°–185° byd 40 NM
187°–197° byd 40 NM
217°–221° byd 40 NM
260°–320° byd 40 NM
350°–039° byd 40 NM