JACKPOT/HAYDEN FLD (Ø6U) 0 E UTC–7(–6DT) N41°58.55′ W114°39.48′ **SALT LAKE CITY**
5224 B NOTAM FILE RNO **H–3D, L–11C**

RWY 15–33: H6180X60 (ASPH) S–12.5 MIRL 0.8% up NW
RWY 15: REIL. PAPI(P2L)—GA 4.0° TCH 40′. Trees.
RWY 33: REIL. PAPI(P2L)—GA 3.5° TCH 40′. Hill.

SERVICE: **LGT** SS–SR. Bcn vis ltd fm west. ACTVT REIL Rwy 15 and Rwy 33; PAPI Rwy 15 and Rwy 33; MIRL Rwy 15–33—CTAF.

AIRPORT REMARKS: Attended on call. Fuel not avbl. Bird hazard east of arpt at ponds. Emergency contact 208–731–2447. If no wind conds, rcmd dep Rwy 15, arr Rwy 33 for slope. Terrain obstns lctd S and W of arpt.

AIRPORT MANAGER: 775-755-2447

WEATHER DATA SOURCES: AWOS–AV 120.00 (775) 755–2297.

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE TWF.

TWIN FALLS (VL) (H) VORTACW 113.1 TWF Chan 78 N42°28.79′ W114°29.37′ 176° 31.1 NM to fld. 4149/18E.
VOR unusable:
000°–010° byd 40 NM blo 7,000′
000°–010° byd 50 NM
011°–015° byd 40 NM
040°–091° byd 40 NM
092°–102° byd 40 NM blo 16,500′
092°–102° byd 77 NM
103°–106° byd 40 NM
107°–117° byd 40 NM blo 14,000′
107°–117° byd 64 NM blo 22,000′
118°–171° byd 40 NM
120°–160° byd 35 NM blo 12,000′
172°–182° byd 40 NM blo 13,000′
172°–182° byd 55 NM
183°–185° byd 40 NM
186°–196° byd 40 NM blo 10,600′
186°–196° byd 57 NM
197°–230° byd 40 NM
TACAN AZIMUTH unusable:
120°–160° byd 35 NM blo 12,000′
DME unusable:
120°–160° byd 35 NM blo 12,000′