YERINGTON MUNI (O43) 1 N UTC–8(–7DT) N39º00.32´ W119º09.39´
4382 B TPA—5182(800) NOTAM FILE RNO

SAN FRANCISCO
H–3C, L–9A
IAP

RWY 02–20: H5822X75 (ASPH) S–24, D–32 MIRL
RWY 02: REIL. PAPI(P2L)—GA 3.0º TCH 40´. Antenna.
RWY 20: REIL. PAPI(P2L)—GA 3.0º TCH 40´. Trees.

SERVICE: **FUEL** 100LL **LGT** ACTVT REIL Rwy 02 and 20; MIRL Rwy 02–20—CTAF. PAPI Rwy 02 and 20 on consly. Rwy 02 PAPI unusbl byd 3.0 NM fm rwy thr due to trrn.

AIRPORT REMARKS: Attended Mon–Fri 1500–0200Z‡, Sat–Sun irregularly.

AIRPORT MANAGER: 775-431-4534

COMMUNICATIONS: CTAF/AUNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.

HAZEN (L) (L) VORTAC 114.1 HZN Chan 88 N39º30.98´ W118º59.86´ 177º 31.5 NM to fld. 4086/17E.

VOR portion unusable:
300º–320º byd 30 NM blo 9,500´