SHIPROCK AIRSTRIP (5V5) 5 S UTC–7(–6DT) N36°41.86′ W108°42.06′ **DENVER**
5273 B NOTAM FILE ABQ **H–4K, L–8H**
RWY 02–20: H5214X75 (ASPH) S–11 PCN 3 F/D/Y/T MIRL 0.9% up S
RWY 02: PAPI(P2L)—GA 3.0° TCH 45′. Pole.
RWY 20: PAPI(P2L)—GA 3.0° TCH 44′.
SERVICE: **LGT** ACTVT MIRL Rwy 02–20—CTAF.
AIRPORT REMARKS: Unattended. Rwy 02–20 ditch NW of rwy entire len. Parl Twy A: cond poor; unmkd; sfc cracks with grass and loose aggregate. Emerg and maint coord — 505–371–8354/505–908–7961.
AIRPORT MANAGER: (505) 728-2804
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE FMN.
RATTLESNAKE (VH) (H) VORTACW 115.3 RSK Chan 100 N36°44.90′ W108°05.93′ 250° 29.2 NM to fld. 5821/14E.
VOR unusable:
007°–017° byd 40 NM blo 18,000′
018°–041° byd 40 NM
042°–062° byd 40 NM blo 15,000′
042°–062° byd 63 NM blo 20,000′
063°–066° byd 40 NM
067°–077° byd 40 NM blo 14,000′
067°–077° byd 75 NM
078°–094° byd 40 NM
095°–105° byd 40 NM blo 18,000′
106°–119° byd 40 NM blo 11,500′
106°–119° byd 62 NM blo 12,500′
106°–119° byd 76 NM
120°–125° byd 40 NM
235°–255° byd 40 NM blo 12,000′
235°–255° byd 84 NM blo 28,000′
256°–274° byd 40 NM
275°–285° byd 40 NM blo 30,000′
286°–327° byd 40 NM
328°–338° byd 40 NM blo 15,000′
344°–356° byd 40 NM blo 16,300′
344°–356° byd 66 NM
357°–006° byd 40 NM

SIERRA BLANCA RGNL (See RUIDOSO on page 461)