TUCUMCARI MUNI (TCC)(KTCC) 6 E UTC–7(–6DT) N35°10.97′ W103°36.19′
4065 B NOTAM FILE TCC MON Airport
RWY 03–21: H7104X100 (ASPH) S–25 PCN 10 F/C/Y/T MIRL
RWY 21: VASI(V4L)—GA 3.0° TCH 52′.
RWY 08–26: H4600X60 (ASPH) S–12 PCN 6 F/D/Y/T MIRL
0.6% up W
SERVICE: **FUEL** 100LL, JET A+ **LGT** ACTVT VASI Rwy 21; MIRL Rwy 03–21 and Rwy 08–26—CTAF.
AIRPORT REMARKS: Attended 1400–0000Z‡, clsd fed hol. Aft hr fuel self svc with credit card.
AIRPORT MANAGER: 575-461-3229
WEATHER DATA SOURCES: ASOS 119.275 (575) 461–4940.
COMMUNICATIONS: CTAF/UNICOM 122.95
Ⓡ **ALBUQUERQUE CENTER APP/DEP CON** 126.85
CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4561.
AIRSPACE: CLASS E svc 1500–2300Z‡; other times CLASS G.
RADIO AIDS TO NAVIGATION: NOTAM FILE TCC.
(VH) (H) VORTACW 113.6 TCC Chan 83 N35°10.93′ W103°35.91′ at fld. 4035/12E.
VOR unusable:
125°–174° byd 40 NM
175°–193° byd 40 NM blo 12,500′
194°–227° byd 40 NM
228°–238° byd 40 NM blo 11,000′
228°–238° byd 46 NM
239°–249° byd 40 NM
250°–261° byd 40 NM blo 7,700′
250°–261° byd 46 NM blo 18,000′
262°–273° byd 40 NM
274°–284° byd 40 NM blo 18,000′
285°–355° byd 40 NM

ALBUQUERQUE
H–6G, L–15A
IAP

