
CENTENNIAL AIRPORT (APA) ARRIVAL ALERT

Landing South RWY 17R and RWY 17L




Pilots confuse RWY 17L for RWY 17R.

**Not for Navigational Purposes
For Situational Awareness Only**

CENTENNIAL AIRPORT (APA) ARRIVAL ALERT

Landing North RWY 35L and RWY 35R



Pilots confuse RWY 35R for RWY 35L.

**Not for Navigational Purposes
For Situational Awareness Only**

Centennial Airport Voluntary Noise Abatement Guidelines*****IN ALL CASES SAFETY AND ATC INSTRUCTIONS TAKE PRECEDENCE*****


The following guidelines are recommended practices to minimize sound levels in the vicinity of Centennial Airport.

KAPA Noise Office – 303-790-0598

Full Noise Abatement Guide: <https://centennialairport.com/noise-abatement-guide>

General Guidelines:

- Traffic Pattern Altitude 6,885 ft. MSL (1,000 ft. AGL)
- Avoid Noise Sensitive Areas (shown below)
- Avoid Flight Training Operations between 2200-0700L
- Make Power Changes Slowly
- Remain in Preferred Pattern Area (shown below)
- If traffic pattern volume becomes saturated causing an extended pattern North of Arapahoe Road or South of Lincoln Avenue consider returning at a less busy time to remain within the depicted traffic pattern area.



Office of Primary Responsibility (OPR): Arapahoe County Public Airport Authority
Contact Information: (303) 218-2919
Modified: June 2025