
MONTEREY REGIONAL AIRPORT (MRY) ARRIVAL ALERT

Landing Northwest RWY 28L and RWY 28R




RWY 28L/R centerlines separated by 500 feet. Pilots in the north traffic pattern and cleared to land RWY 28L sometimes incorrectly land on RWY 28R.

Not for Navigational Purposes
For Situational Awareness Only

Office of Primary Responsibility (OPR): ATO, Runway Safety
Contact Information: (202) 856-1942
Original: January 2024

HARRY REID INTERNATIONAL (LAS) ARRIVAL ALERT

Landing South
RWY 19L and RWY 19R



Pilots on visual approach to RWY 19L or RWY 19R incorrectly align with the parallel runway when joining final from the curved base leg. Runways are 950 ft apart and 150 ft wide with displaced thresholds.

Not for Navigational Purposes
For Situational Awareness Only

Office of Primary Responsibility (OPR): ATO, Runway Safety
Contact Information: (202) 856-1942
Original: December 2025