
OXNARD AIRPORT (OXR) ARRIVAL ALERT

Wrong Airport Landing Landing West OXR and Camarillo Airport (CMA)



Similar Runway Alignment. Pilots arriving OXR from the east, be aware that it is located approx. 5.5 NM west-southwest of (beyond) CMA. Pilots have inadvertently landed on CMA Rwy 26 instead of OXR Rwy 25.

**Not for Navigational Purposes
For Situational Awareness Only**

Office of Primary Responsibility (OPR): ATO, Runway Safety
Contact Information: (424) 405-7766

Original: February 2026