

KASIGLUK (ZØ9)(PFKA) 2 S UTC-9(-8DT) N60°52.40' W162°31.46'

48 NOTAM FILE ENA

RWY 17-35: 3000X60 (GRVL-DIRT) MIRL 0.77 up S

RWY 17: Brush.

RWY 35: Brush.

SERVICE: LGT ACTVT MIRL Rwy 17-35—CTAF.

AIRPORT REMARKS: Unattended. Birds on and in/ovf arpt. Rwy condition not monitored, recommend visual inspection prior to using. Wind turbines within the tfc pat. Lgts at top of twr, not blades. Rwy 17-35 slopes up to S end 1% grade. Rwy 17 first 200 ft very soft when wet.

AIRPORT MANAGER: (907) 543-2498


COMMUNICATIONS: CTAF 122.9

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 125.2

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) (H) VORTACW 114.1 **BET** Chan 88 N60°47.09' W161°49.46' 271° 21.2 NM to fld. 105/14E.

BETHEL
L-3C
IAP



KASILOF

ENCELEWSKI LAKE SPB (AK5) 5 S UTC-9(-8DT) N60°15.33' W151°18.18'

MC GRATH

230 NOTAM FILE ENA

WATERWAY 09W-27W: 3500X500 (WATER)

SEAPLANE REMARKS: Unattended. Public access at N end of lake. Windssock located midlake on W side.

AIRPORT MANAGER: 907-398-2201

COMMUNICATIONS: CTAF 122.9

KASILOF (5KS) 2 N UTC-9(-8DT) N60°21.03' W151°15.77'

ANCHORAGE

125 NOTAM FILE ENA

RWY 01-19: 2400X60 (GRVL)

RWY 01: Trees.

RWY 19: Brush.

AIRPORT REMARKS: Unattended. State maintenance on irregular basis. Rwy cond not monitored, recommend visual inspection prior to use.

All-terrain vehicle traffic may be on rwy. There are 3 inch deep circular ruts from all-terrain vehicle traffic on the rwy. Rwy 01 edge not marked.

The windssock is below the tree line and may be unreliable.

AIRPORT MANAGER: 907-262-1187

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE ENA.

KENAI (H) (H) VORW/DME 117.6 **ENA** Chan 123 N60°36.88' W151°11.71' 168° 16.0 NM to fld. 115/19E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737. Lcl to Kenai FSS dial 283-7211.

