

**TRIDENT BASIN SPB** (T44) 0 N UTC-9(-8DT) N57°46.85' W152°23.48'

**KODIAK**

00 NOTAM FILE ENA

**WATERWAY 02W-20W:** 4400X200 (WATER)

**SERVICE:** FUEL 100LL

**SEAPLANE REMARKS:** Attended continuously. Fuel avbl with credit card. Reef exposed at both ends of waterway on low tides.

Birds invof ldg basin. Boats occasionally use spb waterlane. Pilots arriving/departing Trident Basin must ctc Kodiak twr for tfc advisories and/or special VFR clearance. When twr clsd pilots will self announce on CTAF.

**AIRPORT MANAGER:** 907-486-8060

**COMMUNICATIONS:** CTAF 119.8 UNICOM 122.8

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.

**KOKHANOK** (9K2)(PFKK) 2 SW UTC-9(-8DT) N59°26.00' W154°48.16'

**KODIAK**

115 B NOTAM FILE ILI

**L-21, 3D**

**RWY 07-25:** 3300X75 (GRVL) MIRL

**IAP**

**RWY 07:** REIL. PAPI(P4L)—GA 3.0° TCH 20'. Tree.

**RWY 25:** REIL. PAPI(P4L)—GA 4.0° TCH 23'. Road.

**SERVICE:** LGT ACTIVATE PAPI and REIL Rwy 07 and 25, MIRL Rwy 07-25, rotating bcn and windcone—CTAF.

**AIRPORT REMARKS:** Unattended. Rwy not monitored, visual inspection prior to use. Horses on or invof rwy. 30' unlit twr approximately 300' north of Rwy 07-25.

**AIRPORT MANAGER:** 907-571-1261

**COMMUNICATIONS:** CTAF 122.9

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 118.8

**RADIO AIDS TO NAVIGATION:** NOTAM FILE AKN.

**KING SALMON (H) VORTACW** 112.8 AKN Chan 75 N58°43.48'

W156°45.14' 038° 73.9 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'


130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.



**KOLIGANEK** (JZZ)(PAJZ) 1 E UTC-9(-8DT) N59°43.61' W157°15.62'

**KODIAK**

272 B NOTAM FILE JZZ

**L-3C**

**RWY 09-27:** 3300X75 (GRVL) MIRL 1.0% up E

**IAP**

**RWY 09:** PAPI(P4R)—GA 3.0° TCH 39'. Brush.

**RWY 27:** PAPI(P4L)—GA 3.5° TCH 27'. Brush.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 09:** TORA-3300 TODA-3300 ASDA-3300 LDA-3300

**RWY 27:** TORA-3300 TODA-3300 ASDA-3300 LDA-3300

**SERVICE:** LGT ACTVT MIRL Rwy 09-27, PAPI Rwy 09 and Rwy 27, and rot bcn—CTAF.

**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to use. Rwy 09-27 numerous heaves and humps. Rwy sloughing off into tundra. Rwy slopes down toward west end. Rwy 09 and Rwy 27 thld marked with lgts.

**AIRPORT MANAGER:** 907-842-5511

**WEATHER DATA SOURCES:** AWOS-3P 118.525 (907) 596-3302. (WX CAM)

**COMMUNICATIONS:** CTAF 122.9

**KEMUK MOUNTAIN RCO** 122.55 (DILLINGHAM RADIO) Opr

1645-0845Z†, other times ctc Kenai FSS.

**ANCHORAGE CENTER APP/DEP CON** 282.35 132.75

**RADIO AIDS TO NAVIGATION:** NOTAM FILE DLG.

**DILLINGHAM (H) VORV/DME** 116.4 DLG Chan 111 N58°59.65'

W158°33.13' 026° 59.3 NM to fld. 81/15E.

**COMM/NAV/WEATHER REMARKS:** For a LD call to Dillingham FSS dial 907-842-5275. For a toll free call to Kenai FSS dial 1-866-864-1737.

