

LAZY BAY

ALITAK SPB (ALZ) 0 S UTC-9(-8DT) N56°53.97' W154°14.87'

KODIAK

00 NOTAM FILE ENA

WATERWAY NE-SW: 10000X1000 (WATER)

SEAPLANE REMARKS: Unattended. E-W prevailing winds. Subject to swells in Easterly winds. Aft beaching area is a gravel area east side of cannery. Dock in front of beaching area is hazardous to acft. Ltd para-glider activity during summer months. Heavy bird activity noted in area. Windsock located on old amphibian dock.

AIRPORT MANAGER: 206-285-6800

WEATHER DATA SOURCES: (WX CAM) (TWEB ODK 117.1).

COMMUNICATIONS: CTAF 122.8

RADIO AIDS TO NAVIGATION: NOTAM FILE ADQ.

KODIAK (H) ABVORWME 117.1 ODK Chan 118 N57°46.50'

W152°20.39' 216° 81.4 NM to fid. 133/14E. **TWEB.**

VOR portion unusable:

190°-310° byd 20 NM blo 12,000'

190°-310° byd 15 NM blo 7,000'

DME portion unusable:

040°-046° byd 030 blo 3,000'

154°-266° byd 15 NM abv 7,000'


154°-266° byd 20 NM blo 12,000'

266°-305°

305°-340° byd 15 NM blo 7,000'

305°-340° byd 20 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



LENA POINT N58°23.30' W134°45.72'

JUNEAU

RCO —122.25 (JUNEAU FSS)

L-1B

LEVEL ISLAND N56°28.06' W133°04.99' NOTAM FILE SIT.

JUNEAU

(H) ABVOR/DME 116.5 LVD Chan 112 229° 19.3 NM to Point Baker. 98/20E.

H-1C, L-1C

VOR/DME unusable:

038°-098° byd 35 NM blo 9,000'

098°-138° byd 25 NM blo 7,000'

178°-208° byd 35 NM blo 6,000'

268°-328° byd 25 NM blo 9,000'

328°-358° byd 30 NM blo 7,000' and byd 35 NM blo 8,000'

358°-038° byd 35 NM blo 12,000'

wx cam

RCO 122.3 (SITKA RADIO)

LEVELOCK (9Z8) 1 NNW UTC-9(-8DT) N59°07.63' W156°51.59'

KODIAK

56 B NOTAM FILE ENA

L-21, 3C

RWY 01-19: 3284X60 (GRVL-DIRT) MIRL

RWY 01: Brush.

RWY 19: Brush.

SERVICE: LGT ACTIVATE MIRL Rwy 01-19 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored. Recommend visual inspection prior to ldg. Rwy 01-19 and shoulders soft and muddy when wet. Multiple 2"-4" ruts on rwy edges and circular ruts near rwy thlds. Windsocks in soft soil, may be unreliable. Safety areas byd thlds sinking soft sand use only as emergency overrun.

AIRPORT MANAGER: 907-246-3325

COMMUNICATIONS: CTAF 122.9 UNICOM 122.95

RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.

KING SALMON (H) VORTAC 112.8 AKN Chan 75 N58°43.48'

W156°45.14' 336° 24.4 NM to fid. 95/16E.

TACAN antenna offset 150' SE

TACAN AZIMUTH unusable:

122°-142° blo 2,900'

122°-142° byd 15 NM

335°-350° byd 35 NM blo 3,500'

DME unusable:

335°-350° byd 35 NM blo 3,500'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

