

NAKNEK**NAKNEK** (5NK) 1 N UTC-9(-8DT) N58°44.08' W157°01.51'**KODIAK**

70 NOTAM FILE ENA

RWY 08-26: 1950X50 (GRVL)**RWY 08:** Brush.**RWY 26:** Brush.**RWY 14-32:** 1836X45 (GRVL) 3.0% up SE**RWY 14:** Brush.**RWY 32:** Brush.**SERVICE:** S3 **FUEL** 100LL **LGT** Airport unlit.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Windsock unreliable. Acft on east side of Rwy 14-32 tied down in safety area. Road parallel to and 45' east of Rwy 32 centerline. Uncontrolled vehicular tfc on rwys. No line of sight between rwys or waterways. Float acft departing northwest lake to East, cross arpt at low alt. Acft not visible until airborne. Rwy 08-26 rocks exceeding 2" diameter and ruts 6". Rwy 08 slopes downhill to east. Rwy 14-32 rocks exceeding 2"-3" in diameter and 3" ruts. First 200' Rwy 32 soft when wet. First 400' Rwy 32 slopes downhill.

AIRPORT MANAGER: 907-246-3325**COMMUNICATIONS:** CTAF 122.9**RADIO AIDS TO NAVIGATION:** NOTAM FILE AKN.**KING SALMON (H) VORTACW** 112.8 AKN Chan 75 N58°43.48' W156°45.14' 258° 8.6 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'

130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

COMM/NAV/WEATHER REMARKS: For a toll-free call to Kenai FSS dial 1-888-864-1737.**WATERWAY 08W-26W:** 2000X300 (WATER)**SEAPLANE REMARKS:** Unattended. E apch to lake over Rwy 14-32 Naknek arpt and Tibbetts arpt. Ramp. No line of sight between rwys or waterways. Rwy 08W-26W not on arpt property and is not owned or opr by the state of Alaska.