

PEDRO BAY (4KØ) 1 W UTC-9(-8DT) N59°47.82' W154°07.80'

84 B NOTAM FILE ILI

RWY 09-27: 3002X60 (GRVL-DIRT) MIRL 0.6% up W

RWY 09: Tree. Rgt tfc.

RWY 27: Road.

SERVICE: LGT ACTIVATE MIRL Rwy 09-27, rotating bcn, and windsock light—CTAF.

AIRPORT REMARKS: Unattended. High mountainous terrain N of arpt. Strong winds create severe turbulence and possible wind shear at arpt. Rwy soft during break-up and freeze-up, also after rainy periods. Rwy 09-27 marked with reflective cones and thld panels, some panels damaged.

AIRPORT MANAGER: 907-571-1261

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE ILI.

ILIAMNA NDB/DME (HW) 411 ILI Chan 91 N59°44.88'
W154°54.58' 069° 23.8 NM to fld. 168/14E.

DME unusable:

010°-020° byd 20 NM blo 12,000'

020°-050° byd 25 NM blo 13,000'

270°-300° byd 25 NM blo 7,000'

300°-320° byd 25 NM blo 8,000'

KODIAK

L-3D

