

PORTAGE CREEK (A14)(PAOC) 0 E UTC-9(-8DT) N58°54.39' W157°42.67'

KODIAK

129 NOTAM FILE DLG

RWY 10-28: 1920X60 (GRVL-DIRT) 1.5% up E

RWY 10: Brush.

RWY 28: Brush.

RWY 01-19: 1470X60 (GRVL-DIRT) 1.4% up N

RWY 01: Trees.

RWY 19: Brush.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using; no maint on arpt. Rwy 01-19 sfc ruts 4" to 6" deep, 300' from thld Rwy 01 where acft turn around for tkf. Rwy 10-28 very soft with deep loose grvl. First 200' of Rwy 28 CLOSED with brush growing on edges. Brush and trees encroaching on all rwy sfc. Rwys very soft, deep ruts may develop when sfc wet. Rwy 01-19 marked with reflective orange cones. Rwy 10 marked with reflective orange cones. Slopes up to E end 1.5%. No line of sight btn rwy ends. Rwy 10 and Rwy 01 safety areas soft, may be unusable.

Rwy 28 safety area eroding near bluff.

AIRPORT MANAGER: 907-842-5511

COMMUNICATIONS: CTAF 122.9

KEMUK MOUNTAIN RCO 122.55 (DILLINGHAM RADIO) Opr


1645-0845Z±, other times ctc Kenai FSS.

RADIO AIDS TO NAVIGATION: NOTAM FILE DLG.

DILLINGHAM (H) VOR/DME 116.4 DLG Chan 111 N58°59.65' W158°33.13'

086° 26.7 NM to fld. 81/15E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



PORTAGE GLACIER – PORTAGE VISITOR CENTER POR N60°47.07' W148°50.47'

ASOS 135.45 (907) 783-2626 Test ASOS elev 103 ft msl.

ANCHORAGE

L-1A, 3D, 4G