

POINT HOPE (PHO)(PAPO) 2 SW UTC-9(-8DT) N68°20.93' W166°47.96'

CAPE LISBURNE

19 B NOTAM FILE PHO

H-1A, L-4H

RWY 01-19: H3992X75 (ASPH) MIRL

IAP

RWY 01: VASI(V4L)—GA 3.0° TCH 25'.

RWY 19: VASI(V4L)—GA 3.0° TCH 27'.

SERVICE: LGT ACTIVATE MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to landing. Fuel avbl emerg only. Lateral cracks 1-3" wide across width of rwy spaced 200'-500' length of rwy.

AIRPORT MANAGER: 907-442-3147**WEATHER DATA SOURCES:** AWOS-3P 118.325 (907) 368-2128. (WX CAM)**COMMUNICATIONS:** CTAF 122.8


POINT HOPE RCO 122.25 (KOTZEBUE RADIO)

ANCHORAGE CENTER APP/DEP CON 119.65 363.25

RADIO AIDS TO NAVIGATION: NOTAM FILE PHO.

NDB (HW) 221 PHO N68°20.68' W166°47.89' at fld.
14/11E, unmonitored.

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.

**POINT LAY LRRS** (PIZ)(PPIZ) P (AF) 1 S UTC-9(-8DT) N69°43.97' W163°00.32'

CAPE LISBURNE

29 B NOTAM FILE PIZ

H-1A, L-4H

RWY 05-23: 4500X100 (GRVL) MIRL

IAP

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 35'. Road.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 35'.

SERVICE: LGT ACTIVATE MIRL Rwy 05-23, PAPI and REIL Rwy 05 and Rwy 23 and rotating bcn—122.8.

AIRPORT REMARKS: Unattended. Cold temperature restricted airport. Altitude correction required at or below -33C/-27F.

AIRPORT MANAGER: (907) 852-0489**WEATHER DATA SOURCES:** AWOS-3P 135.65 (907) 833-3112. (WX CAM)**COMMUNICATIONS:** CTAF 122.8

POINT LAY RCO 122.4 (BARROW RADIO)

ANCHORAGE CENTER APP/DEP CON 119.65 363.25

RADIO AIDS TO NAVIGATION: NOTAM FILE PIZ.

NDB (HW) 362 PIZ N69°44.19' W162°59.78' at fld. 14/15E.

COMM/NAV/WEATHER REMARKS: Local call to Barrow FSS dial 852-2511. For a toll free call to Fairbanks FSS call 1-866-248-6516.

