228 ALASKA

DUTCH LANDING STRIP (88AK) PVT O N UTC-9(-8DT) N60°32.42′ W150°52.08′ ANCHORAGE

300 NOTAM FILE Not insp. **RWY 07–25:** 1300X100 (GRVL)

RWY 07: Trees.

RWY 25: Trees. Rgt tfc.
AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: 907-398-8999

COMMUNICATIONS: CTAF 122.5

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

LAKEWOOD AIRSTRIP (53AK) PVT 5 NE UTC-9(-8DT) N60°32.03′ W150°51.39′ ANCHORAGE

299 NOTAM FILE Not insp. RWY 02–20: 1200X60 (GRVL)

RWY 02: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Rwy 02–20 not plowed durg winter, silty sand base unusbl durg breakup. Rwy 02–20

sand/gravel.

AIRPORT MANAGER: 936-443-9072 Communications: CTAF 122.5

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

SCOOTERS LANDING STRIP (AK84) PVT 2 W UTC-9(-8DT) N60°31.77′ W150°49.85′ ANCHORAGE

259 NOTAM FILE Not insp. **RWY 08–26**: 2400X80 (GRVL)

AIRPORT REMARKS: Unattended. PPR arpt rstd to owner or owner invited guests. No acft svcs avbl. Rwy conditions not monitored. Fly pat south of E–W rwy, twrs north. Pilots to conduct rwy visual inspection prior to use. Maintenance personnel and equipment have right of way. Wildlife invof rwy. Be alert, dsplcd thlds exist. Trees and p–lines penetrate apch sfcs. Arpt not fenced.

AIRPORT MANAGER: 907-398-9849
COMMUNICATIONS: CTAF 122.5

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1–866–864–1737. Advisory frequency: 122.5.

STERLING AIR PARK (4ØAK) PVT 2 NW UTC-9(-8DT) N60°33.45′ W150°50.61′ **ANCHORAGE**

333 NOTAM FILE Not insp. RWY 08–26: 1809X60 (GRVL) AIRPORT REMARKS: Unattended. AIRPORT MANAGER: 907-262-5100 COMMUNICATIONS: CTAF 122.5

 $\label{lem:comm/nav/weather remarks: For a toll free call to Kenai FSS dial $1-866-864-1737$.$

STEVENS VILLAGE (SVS)(PFSV) 1 NNE UTC-9(-8DT) N66°01.03′ W149°03.26′ 328 B NOTAM FILE FAI

FAIRBANKS H-1B, L-4J

RWY 05-23: 4000X75 (GRVL-DIRT) M

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.

SERVICE: LGT ACTVT REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05–23—CTAF. ACTVT Rotg beacon—CTAF.

AIRPORT REMARKS: Unattended. Rwy cond unmnt; rcmd visual insp bfr Indg. Clsd rwy 1 NM W. Snow removal ops—CTAF. Rwy 05–23 marked with lgts & cones.

AIRPORT MANAGER: 907-451-5280 COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE FAI.

FAIRBANKS (H) (H) VORTACW 108.6 FAI Chan 23 N64°48.00′ W148°00.72′ 320° 77.8 NM to fld. 1526/21E.

TACAN AZIMUTH unusable:

065°-100° byd 30 NM

270°-330° byd 10 NM blo 10,000′

270°-330° byd 10 NM 270°-330° byd 30 NM

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial

