

AKIACHAK SPB (KKI) 0 S UTC-9(-8DT) N60°54.47' W161°26.10'

MC GRATH

18 NOTAM FILE ENA

WATERWAY E-W: 5000X300 (WATER)

WATERWAY NW-SE: 5000X500 (WATER)


SEAPLANE REMARKS: Unattended. No services or dock. Beaching area adjacent to village. Seaplanes land NW-SE in lagoon, takeoff E-W in river. 60' trees at either end of the water landing area. Shoaling in the landing area. Be aware of possible shallow water. Be alert of arpt tfc NW of waterway area. River has tidal influence. Be alert of tidal flats invof landing and beach area. Inspect before landing.

COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) (H) VORTACW 114.1 BET Chan 88 N60°47.09' W161°49.46' 043° 13.6 NM to fld. 105/14E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



AKIAK (AKI)(PFAK) 0 SW UTC-9(-8DT) N60°54.17' W161°13.84'

MC GRATH

40 B NOTAM FILE ENA

RWY 03-21: 3200X76 (GRVL) MIRL

RWY 03: Trees.

RWY 21: Trees.

SERVICE: LGT ACTIVATE MIRL Rwy 03-21-CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Numerous arpts in the vicinity, pilots are requested to self-announce on CTAF prior to taxiing on rwy for departure, leaving the rwy, and within 10 NM of the arpt when approaching to land. Waterfowl on and invof arpt. Windssock unreliable. Rwy 03 and Rwy 21 NSTD markings, rwys marked with cones and reflective thld markers. Brush obscures rwy lgt.

AIRPORT MANAGER: (907) 543-2498


COMMUNICATIONS: CTAF 122.9

ANCHORAGE CENTER APP/DEP CON 125.2

RADIO AIDS TO NAVIGATION: NOTAM FILE BET.

BETHEL (H) (H) VORTACW 114.1 BET Chan 88 N60°47.09' W161°49.46' 054° 18.8 NM to fld. 105/14E.

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.



MC GRATH

L-3C

IAP