ALASKA 41

AMBLER (AFM)(PAFM) 1 N UTC-9(-8DT) N67°06.37′ W157°51.43′

293 B NOTAM FILE AFM

RWY 01-19: 4000X75 (GRVL-DIRT) MIRL 0.5% up N RWY 01: PAPI(P4R)—GA 3.0° TCH 25'. Trees.

RWY 19- Trees

RWY 10-28: 2400X60 (GRVL-DIRT) MIRL 1.1% up W SERVICE: LGT ACTIVATE PAPI Rwy 01; MIRL Rwy 01-19 and Rwy 10-28; windsock lgts-CTAF. ACTIVATE rotating bcn-CTAF.

AIRPORT REMARKS: Unattended. Rwy conditions not monitored,

recommend visual inspection prior to using. Caribou invof rwys. Rwy 01-19 rwy surface is compacted gravel, rock and dirt. Rwy 10-28 rwy surface is compacted gravel, rock and dirt. Cold temperature airport. Altitude correction required at or below -37C. Rwy 01-19 crowns in center and no line of sight between rwy ends. Rwy 10-28 slopes uphill east to west approximately 80'.

AIRPORT MANAGER: 907-442-3147

WEATHER DATA SOURCES: AWOS-3P 132.1 (907) 445-2146. (WX CAM) **COMMUNICATIONS: CTAF 122.7**

RCO 122.0 (KOTZEBUE RADIO)


ANCHORAGE CENTER APP/DEP CON 119.2

RADIO AIDS TO NAVIGATION: NOTAM FILE OTZ.

KOTZEBUE (H) (H) VORW/DME 115.7 OTZ Chan 104 N66°53.14' W162º32 40' 066° 111.1 NM to fld. 121/15E.

NDB (HW) 403 AMF N67°06.31' W157°51.61' at fld. 258/15E. NOTAM FILE AFM.

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6515.



AMERICAN CREEK (8ØA) 0 N UTC-9(-8DT) N65°06.24' W151°10.63' 513 NOTAM FILE FAI

FAIRBANKS

FAIRBANKS

H-1A, L-4I IAP

RWY 02-20: 1500X70 (TURF-GRVL)

1.3% up N

RWY 02: Tree.

RWY 20: Tree.

AIRPORT REMARKS: Unattended. Be alert winds erratic. Be alert, rwy used as road by mining equipment. Heavy equipment and drag line boom invof rwy, recommend flyby before ldg. No line of sight between rwy ends. Rocks up to 6" in diameter. COMMUNICATIONS: CTAF 122.9