

**FLYING CROWN** (AK12) PVT 6 S UTC-9(-8DT) N61°06.40' W149°51.86'

**ANCHORAGE**

150 NOTAM FILE Not insp.

**RWY 13-31:** 1078X50 (TURF)

**RWY 13:** Thld dsplcd 30'. Trees.

**RWY 31:** Thld dsplcd 798'. Trees. Rgt tfc.

**AIRPORT REMARKS:** Unattended. Rwy conditions unmonitored, visual inspection recommended prior to use. Watch for pedestrians. Multiple sprinkler and equipment on or near rwy. And hill near end of rwys not maintained in winter. Railroad runs parallel to rwy, frequent train traffic. Operations not recommended during train traffic.

**AIRPORT MANAGER:** 907-245-1932

**COMMUNICATIONS:** CTAF 122.9

**RADIO AIDS TO NAVIGATION:** NOTAM FILE ANC.

**ANCHORAGE (H) VOR/DME** 113.15 TED Chan 78(Y) N61°10.07'  
W149°57.61' 125° 4.6 NM to fld. 93/18E.

VOR unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

DME unusable:

041°-091° byd 25 NM blo 15,000'

091°-096° byd 20 NM blo 15,000'

096°-121° byd 25 NM blo 12,500'

121°-146° byd 25 NM blo 9,000'

196°-206° byd 25 NM blo 3,500'

206°-211° byd 25 NM blo 4,000'

211°-221° byd 25 NM blo 3,500'

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.

